

WTC Visual Survey Form

Premise Address: <u>25 Broadway</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>23</u>	AKA's: <u>Greenwich St address also</u>	
Building Owner/Management:		Telephone Number: (212) 344 2035
Name: <u>Chris Benson</u>		FAX: ()
Address:		
On Site Contact:		
Name: <u>Chris Benson</u>		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☒ No		Locations: _____
Air Monitoring ☒ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: broken windows etc

Roof

Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.

Description: _____

Setbacks

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u>22</u>	Debris: ☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Setback at 22 floor replaced.

Date: 1/24/2002Inspection Team: Name: Carli IntermittentAgency: PCD

?

WTC Visual Survey Form

Premise Address: <u>25 Broadway</u>		
Block: Lot:	Residential ☐ Commercial ☒ Mix Use ☐ Other ☐	Name of Building:
# of Stories: <u>23</u>	AKA's: <u>Green St address also</u>	
Building Owner/Management: Name: <u>Chris Benson</u>		Telephone Number: (212) <u>344 2035</u> FAX: ()
Address:		
On Site Contact: Name: <u>Chris Benson</u>		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☒ Yes ☐ No Exterior Survey Performed ☒ Yes ☐ No General Clean Up ☒ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☒ No Locations: _____ Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:			
		Inspected	Debris
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>Broken windows etc</u>			
Roof			
Debris: ☒ No Visible /Fine Layer <u>Light dust</u> ☐ 1/2 to 1" <u>1 dust</u> ☐ > 1" <u>1 dust</u>			
Description: _____			
Setbacks <u>N/A</u> ☒			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: <u>22</u>	Debris: ☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Comments: <u>Setback at 22 floor replaced.</u>			

Date: 1/24/2002

Inspection Team: Name: AME International Inc.
Name: _____

Agency: PCD
Agency: _____

E N T E R E D

24