

WTC Visual Survey Form

1077207

Premise Address: <u>148 Duane St</u>		
Block: <u>146</u>	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐ <u>--</u>	Name of Building:
Lot: <u>14</u>		
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☒ Yes ☐ No	Debris	☒ No Visible/ Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/ Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: _____					
Roof					
Debris: ☒ No Visible/ Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>Access gained through 146 Duane St</u>					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 4/11/2000Inspection by: Name: RammohanAgency: DEP.

Name: _____

Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 11, 2002

Building Owner Name: The Building Owner

Address: 148 Duane Street
NYC NY

Subject: 148 Duane Street

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,


R. Radhakrishnan, P.E.
Director
Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

04/15/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
148..... DUANE STREET..... 1 MANHATTAN 10013 BIN# 1077207
DCP GEOGRAPHICAL INFORMATION:
DUANE STREET 148 - 148 HEALTH AREA : 77 TAX BLK: 146..
CENSUS TRACT: 2011 TAX LOT: 14..
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : PUSCH GLORIA PUSCH GLORIA
CORP. NAME : LPC LANDMARK STATUS: LANDMARK
ADDRESS : 148 DUANE ST DOB LOCAL LAW STATUS: NO
NEW YORK NY 10013-3855
DOF BUILDING INFORMATION:
BLDG SIZE: 0033.00 X 0107.00 TRANS LAND VALUE: 801,000
LOT SIZE: 0033.58 X 0116.08 TAX EXEMPT FLAG : NO
BLDG CLASS : D2 ELEVATOR APT TAX EXEMPT CLASS:
STORIES : 5 CITY OWNERSHIP : NO
FOR CITY } MGMT TYPE: MGMT CODE: UPDATE DATE : 03/25/02
OWNERSHIP } MGMT HOLDER CODE: MGMT CODE NAME:
MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 4/15/ 2 Time: 12:15:57 PM

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date

09/18/2008 02:10:04

Submitted By

Page 2

Linked Requests

Service #	Problem	Problem Date	Address

No Linked Requests for this Service Request Inspection

NYC DEP

Method

Source

Critical Service

Log

Log Type
Entered By

Description
Comments

Log Started

Log Ended

There are no log entries for this service number

End of Report