

WTC Visual Survey Form

1075669

Premise Address: 134 DUANE ST		
Block: 246	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐	Name of Building:
# of Stories: 5	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☒ No Visible / Fine Layer ☐ 1/2 to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					

Date: 4/13/2002

Inspection Team: Name: RAMMOHAN

Agency: DEP

Name: _____

Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 13, 2002

Building Owner Name: The Bldg owner

Address: 134 Duane St.
N.Y., N.Y.

Subject: 134 Duane St

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

Deborah Fae

R. Radhakrishnan, P.E.
Director
Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

04/15/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI031
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
134..... DUANE STREET..... 1 MANHATTAN 10013 BIN# 1075669
DCP GEOGRAPHICAL INFORMATION:
DUANE STREET 134 - 136 HEALTH AREA : 77 TAX BLK: 146..
DUANE STREET 138 - 140 CENSUS TRACT: 2011 TAX LOT: 21...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 2 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 134-138 DUANE STREET #63 134-138 DUANE STREET
CORP. NAME : ANDREWS BUILDING CORP LPC LANDMARK STATUS: LANDMARK
ADDRESS : 666 BROADWAY DOB LOCAL LAW STATUS: NO
NEW YORK NY 10012-2317
DOF BUILDING INFORMATION:
BLDG SIZE: 0075.00 X 0117.00 TRANS LAND VALUE: 2,150,000
LOT SIZE: 0075.00 X 0117.00 TAX EXEMPT FLAG : NO
BLDG CLASS : DO ELEVATOR APT TAX EXEMPT CLASS:
STORIES : 5 CITY OWNERSHIP : NO
UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 4/15/ 2 Time: 12:17:29 PM

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 04/12/2002 05:38 PM

Submitted By

Page 2

Linked Requests

Service #	Problem Location	Problem Date	Address
-----------	------------------	--------------	---------

No Linked Requests for this Service Request Inspection

NYC DEP

Method

Source

Critical Service

Log Type	Entered By	Description Comments	Log Started	Log Ended
----------	------------	----------------------	-------------	-----------

There are no log entries for this service number

End of Report