

WTC Visual Survey Form

1001647

Premise Address: <u>100 Wane</u>		
Block: <u>150</u>	Residential ☐ Commercial ☐	Name of Building: <u>FDNY 4th</u>
Lot: <u>25</u>	Mix Use ☐ Other ☐	<u>Engine Co 7 Ladder 1</u>
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☒ Yes ☐ No	Debris	☒ No Visible/ Fine Layer
South	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/ Fine Layer	☐ ½ to 1" ☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: _____					
Roof					
Debris: ☒ No Visible/ Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 4/13/2002Inspection Team: Name: RAM & SAH Agency: DEP

Name: _____ Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April 13, 2002

Building Owner Name: The Bldg. owner

Address: 100 Duane St.
N.Y., N.Y.

Subject: 100 Duane St.

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

04/15/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI031
 MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
 100..... DUANE STREET..... 1 MANHATTAN 10007 BIN# 1001647
 DCP GEOGRAPHICAL INFORMATION:
 DUANE STREET 100 - 102 HEALTH AREA : 77 TAX BLK: 150..
 DUANE STREET 104 - 104 CENSUS TRACT: 1010 TAX LOT: 25...
 COMMUNITY BD: 101 CONDO :
 MULTI STRUCT: 2 CUI NO :
 DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
 OWNER NAME : FIRE DEPARTMENT FIRE DEPARTMENT
 CORP. NAME : LPC LANDMARK STATUS: LANDMARK
 ADDRESS : 9 METROTECH CTR DOB LOCAL LAW STATUS: NO
 BROOKLYN NY 11201-5431
 DOF BUILDING INFORMATION: TRANS LAND VALUE: 1,125,000
 BLDG SIZE: 0076.00 X 0080.00 TAX EXEMPT FLAG : YES
 LOT SIZE: 0075.75 X 0116.67 TAX EXEMPT CLASS: X1
 BLDG CLASS : Y1 GOVERNMENT INSTALLATIONS CITY OWNERSHIP : YES
 STORIES : 3 UPDATE DATE : 03/25/02
 FOR CITY } MGMT TYPE: MGMT CODE: 220 MGMT CODE NAME: FIRE
 OWNERSHIP } MGMT HOLDER CODE: 220 MGMT HOLDER CODE NAME: FIRE

 PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

~~Service Request Inspection Detail~~

Report Date ~~11/11/2011 1:11 PM~~

~~Submitted By~~

Page 2

Linked Requests

Service #	Problem	Problem Date	Address
	Location		

No Linked Requests for this Service Request Inspection

NYC DEP

Method
Source
Critical Service

Log Log Type Entered By	Description Comments	Log Started	Log Ended
-------------------------------	-------------------------	-------------	-----------

There are no log entries for this service number

End of Report