

WTC Visual Survey Form

Premise Address: 15 CLIFF STREET		
Block:	Residential ☒ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	NYU DORMITORY
# of Stories:	AKA's:	
Building Owner/Management: Rockrose Development		Telephone Number: (917) 709-3030
Name: Pablo Fernandez		FAX: ()
Address:		
On Site Contact: Super / Handyman		
Name: Derek / Symond		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☒ Yes ☐ No	Debris	☒ No Visible/ Fine Layer ☐ ½ to 1" ☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/ Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/ Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/ Fine Layer ☐ ½ to 1" ☐ > 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible/ Debris Layer ☐ ½ to 1" ☐ > 1"					
Description:					
Setbacks N/A ☒					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: 10/18/2002

Inspection Team: Name: R. RAMMOHAN

Agency: NYC DEP.

Name: _____ Agency: _____

ENTERED