

WTC Visual Survey Form

1001619

Premise Address: <u>200 Church.</u>		
Block: <u>147</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>28</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>On east side windows with fine layer of dust.</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>along church st near drains approx 15 sq. ft</u>					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments: <u>DEP</u>					

Date: 4/1/02Inspection Team: Name: RAM & SHAHAgency: DEP.

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

~~APRIL~~ 13, 2002

Building Owner Name: The Building Owners

Address: 200 Church Street
NY NY

Subject: 200 CHURCH STREET

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☐ building facade(s)
- ☐ setback(s)
- ☒ roof East side long drains.
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by ~~October~~ APRIL 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
for R. Radhakrishnan, P.E.
Director
Asbestos Control Program





The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Corona, New York
 11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner
Bureau of Environmental Compliance
 Tel (718) 595-4418
 Fax (718) 595-4422

APR 13th
 February 13th, 2002

Building Owner Name: The bldg owner
Address: 200 CHURCH ST.
MANHATTAN
Subject: 200 CHURCH

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan
 R. Radhakrishnan, P.E.
 Director
 Asbestos Control Program



Page: 1 Document Name: Extra

04/15/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPI431
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
200..... CHURCH STREET..... 1 MANHATTAN 10013 BIN# 1001619
DCP GEOGRAPHICAL INFORMATION:
CHURCH STREET 194 - 206 HEALTH AREA : 77 TAX BLK: 147..
DUANE STREET 127 - 127 CENSUS TRACT: 2010 TAX LOT: 28..
THOMAS STREET 50 - 52 COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 200 CHURCH ST ASSOCIATES 200 CHURCH ST ASSOCIA
CORP. NAME : LPC LANDMARK STATUS: LANDMARK
ADDRESS : 1407 BROADWAY DOB LOCAL LAW STATUS: NO
NEW YORK NY 10018-5100
DOF BUILDING INFORMATION: TRANS LAND VALUE: 2,420,000
BLDG SIZE: 0150.00 X 0050.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0176.08 X 0050.00 TAX EXEMPT CLASS:
BLDG CLASS : 05 OFFICE BUILDING CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 4/15/ 2 Time: 12:16:17 PM

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

~~Service Request Inspection Detail~~

Report Date 04/12/2002

Submitted By

Page 2

Linked Requests

Service #	Problem Location	Problem Date	Address
-----------	------------------	--------------	---------

No Linked Requests for this Service Request Inspection

NYC DEP

Method

Source

Critical Service

Log Log Type Entered By	Description Comments	Log Started	Log Ended
-------------------------------	-------------------------	-------------	-----------

There are no log entries for this service number

End of Report