

Open a new Folder.

**DEPARTMENT OF ENVIRONMENTAL PROTECTION
BUREAU OF ENVIRONMENTAL COMPLIANCE
ASBESTOS AND LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368
JOEL A. MIELE, SR., P.E.
COMMISSIONER**

**BULK
ANALYSIS CHAIN OF CUSTODY**

Incident No.: _____ Date Sampled: 2-23-02
Premise: 165 CHURCH ST. Boro: MANHATTAN
Time: 3:00 am/pm
Inspector: D. SHAM DB Shah
Print Signature

Turnaround Time: Immediate ☒ 24 Hours ☐ 48 Hours ☐ 1 Week ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A060012	Fibrous & Dust	Roof mid section	
2. 20223/A060013	" "	Roof mid section	
3. 20223/A060014	" "	Roof N. W. corner	
4. 20223/A060015	" "	Roof W. section	
5. 20223/A060016	" "	Roof S. E. corner	
6. 20223/A060017	" "	Roof S. W. corner	
7. 20223/A060018	" "	Roof N. E. corner	
8. 20223/A060019	" "	Roof mid section	
9. 20223/A060020	" "	Roof stair side	
10.			

ANALYSIS REQUESTED: Asbestos PLM ☐ Asbestos TEM ☐ Lead ☐

Date	Time	Accepted By	Comments
1.	am pm	Print	
		Sign	
2.	am pm	Print	
		Sign	
3.	am pm	Print	
		Sign	
4.	am pm	Print	
		Sign	
5.	am pm	Print	
		Sign	

DEP ACLP REV 5/00

ENTERED

2/23/02

~~Chambers Street~~

165 Church St

