

1001405

To complete info

WTC Visual Survey Form

Premise Address:		
Block: 134	Residential ☐ Commercial ☐	Name of Building:
Lot: 124	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: <u>inside</u>		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:		
North ☐ N/A	Inspected ☒ Yes ☐ No	Debris ☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>main window at Road Construction</u>		
Roof		
Debris: ☐ No Visible /Fine Layer ☐ 1/2 to 1" <u>light dust</u> ☐ > 1" <u>1 dust</u>		
Description: _____		
Setbacks N/A ☐		
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"	
Comments		

Date: 01/27/2002

Inspection Team: Name: AC
Name: HENRIK

Agency: _____
Agency: _____