

3

WTC Visual Survey Form

Premise Address: <u>199 CHAMBERS ST</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐ <u>SCHOOL</u>	<u>BMCC</u>
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: <u>CUNY</u>		FAX: <u>(212) 346-8766</u>
Address:		
On Site Contact:		Telephone Number: <u>(212) 220-8027</u>
Name: <u>Robert Scott</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
	Inspected	Debris	
North	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
South	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
East	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
West	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
Facade Description: <u>ALL FACADE CLEANED</u>			
Roof			
Debris: ☐ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"			
Description: _____			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Comments <u>The school is reoccupied and also</u>			
<u>to call the engineer to get more information.</u>			

2/4/2002

Inspection Team: Name: Mr. Alphonse J. Horton Agency: NYC DEP
Name: Mr. Horton Agency: NYC DEP

WTC Visual Survey Form

Premise Address: 199 CHAMBERS ST		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐ SCHOOL	BMCC
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name: CUNY		FAX: (212) 346-8766
Address:		
On Site Contact:		Telephone Number: (212) 220-8027
Name: Robert Scott		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected		Debris	
North	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: ALL FACADE CLEANED					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: The Engineer was not available					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"		☐ > 1"
Comments The school is reoccupied and also to call the engineer to get more information.					

11/27/2002

Inspection Team: Name: AL

Name:

Agency:

Agency: