

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
 MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
 155..... CHAMBERS STREET..... 1 MANHATTAN 10007 BIN# 1001504

DCP GEOGRAPHICAL INFORMATION:

CHAMBERS STREET 155 - 155 HEALTH AREA : 77 TAX BLK: 140..
 CENSUS TRACT: 2001 TAX LOT: 9....
 COMMUNITY BD: 101 CONDO :
 MULTI STRUCT: 1 CUI NO :

DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE

OWNER NAME : MOSKOWITZ HERBERT MOSKOWITZ HERBERT
 CORP. NAME : LPC LANDMARK STATUS: NO
 ADDRESS : DOB LOCAL LAW STATUS: NO

PII

DOF BUILDING INFORMATION:

BLDG SIZE; 0025.00 X 0077.00 TRANS LAND VALUE: 608,000
 LOT SIZE: 0025.00 X 0076.58 TAX EXEMPT FLAG : NO
 BLDG CLASS : D2 ELEVATOR APT TAX EXEMPT CLASS:
 STORIES : 5 CITY OWNERSHIP : NO
 UPDATE DATE : 01/12/02
 FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
 OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

 PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 12:01:12 PM



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

February 8, 2002

MOSKOWITZ HERBERT

PII

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

Subject: 155 CHAMBERS STREET, MANHATTAN

Dear Sir/ Madam:

The New York City Department of Environmental Protection in cooperation with the New York State Department of Labor and the United States Environmental Protection Agency has continued inspections/surveys of buildings in the vicinity of the World Trade Center.

During the recent inspections/surveys, visible debris from the collapse of the Towers was observed on the ~~roof, setbacks, and/or~~ facades of the above referenced building. In accordance with previously issued guidelines, copies of which are enclosed, these accumulations must be assessed by a NYC DEP certified investigator to determine whether the material is asbestos-containing material and then cleaned up appropriately.

Building owners are responsible for the cleaning of building exteriors, grounds, and common area. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP.

Sincerely,

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

WTC Visual Survey Form

Premise Address: <u>155 Chambers</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>WINDOWS DIRTY STREET INSPECTION</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>1 NORTH TO 100M 147 CHAMBERS / 121 REAR</u>					
Setbacks N/A ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments <u>NO ALLIES</u>					

Date: 01 / 26 / 2002Inspection Team: Name: AL Agency: _____
Name: HENRICK Agency: _____

A2H2