

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
154..... CHAMBERS STREET..... 1 MANHATTAN 10007 BIN# 1001494

DCP GEOGRAPHICAL INFORMATION:

CHAMBERS STREET 154 - 154

HEALTH AREA : 77 TAX BLK: 137..

CENSUS TRACT: 2002 TAX LOT: 29...

COMMUNITY BD: 101 CONDO :

MULTI STRUCT: 1 CUI NO :

DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE

OWNER NAME : HISAKO RESNICK

HISAKO RESNICK

CORP. NAME :

LPC LANDMARK STATUS: NO

ADDRESS :

PII

DOB LOCAL LAW STATUS: NO

DOF BUILDING INFORMATION:

BLDG SIZE; 0024.00 X 0072.00

TRANS LAND VALUE: 404,000

LOT SIZE: 0023.58 X 0075.00

TAX EXEMPT FLAG : NO

BLDG CLASS : L8 LOFT BUILDING

TAX EXEMPT CLASS:

STORIES : 5

CITY OWNERSHIP : NO

FOR CITY } MGMT TYPE: MGMT CODE:

UPDATE DATE : 01/12/02

OWNERSHIP } MGMT HOLDER CODE:

MGMT CODE NAME:

MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 12:01:05 PM

WTC Visual Survey Form

Premise Address: <u>154 Chambers</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>From Street DEBRIS ON FIRE ESCAPE</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: <u>INSPECTED FROM 147 CHAMBERS / 121 ROAD</u>					
Setbacks <u>N/A</u> ☒					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments <u>No Access</u>					

Date: 01/26/2002Inspection Team: Name: ALName: HENRICK

Agency: _____

Agency: _____

A2K18