

WTC Visual Survey Form

Premise Address: <u>150-152 Chamber Street</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade: <u>Rear</u>					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>Window ledges contained visible debris in the rear.</u>					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: <u>Accumulation of WTC debris observed from 80 Warren St.</u>					
Setbacks <u>N/A</u> ☐					
Floor: <u>2nd</u>	<u>Rear</u>	Debris: ☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____		Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments <u>This inspection was conducted based on a complaint by a tenant who lives at 80 Warren Street and see material was visible from the complainant's rear window.</u>					

Date: 2/28/2002Inspection Team: Name: RammoshanAgency: DEP
Name: _____ Agency: _____

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 02/23/2002 02:37 PM

Submitted By

Page 1

Service # 413585

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 150 CHAMBERS ST 1

10007

Cross Streets HUDSON ST
GREENWICH ST

Compass Direction

Building ID 10014

Block 00137

Lot 7501

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 02/23/2002 14:26

Taken By 7136

PLUMPTRE, ADEWALE

Responsibility BHZ

BANHAZMAT (AIR, NOISE, HAZ. MAT)

Scheduled Date

Inspector

Due Date

Resolution Code

Asset

Avg Insp Duration

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

Priority

Start Date

Inspection Date

☐ No Work Orders Required

Resolution Date

☐ Customer Contact Req

Budget #

Problem Comments

Initial Caller

Last Name

PII

Title MS

First Name, MI

Address 80 WARREN ST

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

PII

Evening Phone

Reference #

Super

212 385 0482

Call Date 02/23/2002 14:26

Caller Comments

BUILDING STILL CONTAINS DUST AND PARTICLES FROM SEPTEMBER 11/PLS RESPOND ASAP

Work Orders

Work Order #
Priority

Activity

Asset

Problem Project

Act Type

Act Group

Initiated

Fr Type Unit ID

Scheduled

To Type

Completed

Unit ID

Source

Maint Type

#

There are no work orders for this service number

Assets

Asset

From Type

Unit ID

To Type

Unit ID

#

Qualifier

There are no assets

Linked Requests

Service #

Problem

Problem Date

Address

Location

No Linked Requests for this Service Request Inspection

150-152 - Back set back on 2nd floor
window site & lodge, Alleyway

Thursday 2/28/02
After 1:00 pm - 5:00 pm
Rain 2/28/02 3:00 - 4:00