

ASBESTOS INSPECTION REPORT

REMISE NO.		STREET				INSPECTION DATE	
146		CHAMBERS STREET				8/17/02	
LOOR	ZIP	BORO CODE	BLOCK	LOT	SQUAD #	BADGE #	
R/F	10007	1	137	33	1	AD10	
INSPECTOR		BLDG TYPE	BASIS OF INSPECT.			PHOTOS TAKEN YES / NO	
ALPHONSO PLUMPTRE			TRU 1262 MND				
CONTRACTORS NAME					SAMPLE NO.		
FIBER CONTROL							
ADDRESS					SAMPLE NO.		
3010 BURNS AVE							
CITY	STATE	ZIP	PHONE	SAMPLE NO.			
WANTAGH	N.Y.	11793	(516) 781-3000				
LABORATORY NAME					OWNERS NAME		
WARREN & PANZER ENGINEERS, PC					MARDIG KACHIAN RICHAR		
ADDRESS					CITY		
228 E. 45TH ST					N.Y.		
STATE	ZIP	PHONE	TIME OF INSPECTION FROM: TO:				
N.Y.	10017	(212) 922-0077	N.Y. ZIP 10007 PHONE 130 am/pm TO: 530 am/pm				
CONTACT PERSON:							
INSPECTION DISCLOSED:							

It took us about 2 hours to clean the roof due to lots of debris underneath wooden deck. The wooden deck had to be raised up and there were lots of accumulation of debris that had been buried for a long time. After thorough cleaning and washing the roof was later inspected and was free of visible debris. The Contractor continued with the facade cleaning including the rear setback which was not part of the first measurement. The facade was cleaned and the rear setback and were later inspected to be free of visible debris.

NOV #	#INFRCTIONS					RESULT CODE
						5
NOV #						SUPERVISORS INITIALS
						RP

BORO 1 - MANHATTAN 2 - BRONX 3 - BROOKLYN 4 - QUEENS 5 - RICHMOND

BLDG TYPE A > 6 Stories B < 6 Stories C Single Family D School E Hospital F Public Owned Property

RESULT CODES 1 - Violation Issued 2 - No Violations Issued 3 - No Access 4 - Project not Started (No NOV) 5 - Project Completed (No NOV)

ACP 3093

FILE