

Page: 1 Document Name: Extra

01/30/02 N.Y.C. DEPARTMENT OF BUILDINGS BISPIQ31
MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
146..... CHAMBERS STREET..... 1 MANHATTAN 10007 BIN# 1001497
DCP GEOGRAPHICAL INFORMATION:
CHAMBERS STREET 146 - 146 HEALTH AREA : 77 TAX BLK: 137..
CENSUS TRACT: 2002 TAX LOT: 33..
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 1 CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : MARDIG KACHIAN RICHAR MARDIG KACHIAN RICHAR
CORP. NAME : LPC LANDMARK STATUS: NO
ADDRESS : CHAMBERS STREET DOB LOCAL LAW STATUS: YES
NEW YORK NY 10007
DOF BUILDING INFORMATION: TRANS LAND VALUE: 408,000
BLDG SIZE: 0025.00 X 0071.00 TAX EXEMPT FLAG : NO
LOT SIZE: 0025.08 X 0076.08 TAX EXEMPT CLASS:
BLDG CLASS : L8 LOFT BUILDING CITY OWNERSHIP : NO
STORIES : 5 UPDATE DATE : 01/12/02
FOR CITY } MGMT TYPE: MGMT CODE: MGMT CODE NAME:
OWNERSHIP } MGMT HOLDER CODE: MGMT HOLDER CODE NAME:

PF1 =PREV PF2 =MAIN PF7 = NEW ADDRESS PF8 = NEW BLK/LOT PF9 = NEW BIN

Date: 1/30/ 2 Time: 12:00:12 PM

WTC Visual Survey Form

Premise Address: <u>1146 CUSHMAN BLVD</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☒ Other ☐	
# of Stories: <u>5</u>	AKA's:	
Building Owner/Management:		Telephone Number: <u>(212) 732-9319</u>
Name: <u>MARDIS KACHIAN</u>		FAX: ()
Address: <u>179 WEST ST NY NY 10007</u>		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No		Locations: _____
ACM Clean Up ☐ Yes ☐ No		Locations: _____
Air Monitoring ☐ Yes ☐ No		Locations: _____
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: <u>WINDOWS + LEDS</u> <u>SILVER INSPECTION</u>					
Roof					
Debris: ☒ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments					

Date: 01/26/2002Inspection Team: Name: AL

Agency: _____

Name: HENRIK

Agency: _____

A2H 15