



EL758387640US

February 12, 2002

**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

52 Warren Street Owners Inc., Steven King, Treasurer
122 Chambers Street
New York, NY 10007-1031

Subject: 122 CHAMBERS STREET
52 Warren Street

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP

WTC Visual Survey Form

Premise Address: 52 WARREN ST.		
Block: 136 Lot: 10	Residential ☐ Commercial ☐ Mix Use ☒ Other ☐	Name of Building:
# of Stories: 5	AKA's: 122 CHAMBERS ST.	
Building Owner/Management Name:		Telephone Number: ()
Address:		FAX: ()
On Site Contact Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:							
		Inspected		Debris			
North	☐ N/A	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
South	☐ N/A	☒ Yes	☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
East	☒ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
West	☒ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Facade Description: APPEARS RECENTLY CLEANED							
Roof							
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"							
Description: Inspected from 50 Warren Street.							
Setbacks N/A ☒							
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"				
Comments							

Date: 1/25/2002

 Inspection Team: Name: HORTON HENDRICH
 Name: Penny Theodorellus Agency: NYS DCL
 Agency: NYCDER

Date: 1/30/ 2 Time: 08:30:38 AM