



The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Flushing, New York
 11373-5108

Christopher O. Ward
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of Environmental Compliance

2

AT

May 3, 2002

Dadourian Export Corp.
 Attn: Paul Esposito
 128 Chambers Street
 New York, NY 10007-3514

Subject: 128 CHAMBERS STREET
 85-93 West Broadway

Dear Sir/Madam:

Dadourian Export Corp.
Pres. Alexander Dadourian
Paul Esposito
Rm. 608 / 68 Canana / St
N.Y., N.Y. #10013
(212) 334-0990

The New York City Department of Environmental Protection (DEP) in cooperation with the United States Environmental Protection Agency (USEPA) and the New York State Department of Labor (NYSDOL) has performed a series of exterior building surveys on various buildings in the vicinity of the World Trade Center (WTC). The surveys included the examination of building exteriors including building roofs, facades, setbacks, and other exterior surfaces. These surveys identified locations where debris from the collapse of the WTC was still visible. Our records indicate that visible debris accumulations were observed at the above referenced building (the "Building").

In our previous correspondence, the Department requested an assessment and appropriate clean up of visible debris accumulations. The Department has either not received information regarding your actions to address the debris accumulations or has re-inspected your building and found that visible debris was present.

The USEPA and DEP are continuing their ongoing efforts to improve air quality in lower Manhattan. In this regard, DEP is initiating a program (the "Cleaning Program") to clean the exteriors of certain buildings in the downtown Manhattan area.

Based on visual surveys and analyses of other properties in the area, we are assuming that the debris accumulations noted on the exterior of the Building may include some amount of asbestos-containing material (ACM). DEP would like to include the Building in the Cleaning Program, and clean the facades, roofs, and other exterior surfaces so as to remove such accumulations. The work would be performed by NYSDOL licensed asbestos contractors with DEP and NYSDOL certified workers. The fees and expenses of the asbestos contractor in performing the work will be paid for by the DEP.

The work will be monitored by DEP personnel. An independent third-party air monitoring firm will also be engaged to take air samples at designated points around the perimeter of the working area. The U.S. Occupational Safety and Health Administration (OSHA) will provide oversight for worker safety. The fees and expenses of DEP personnel in monitoring the work and the fees and expenses of the third-party air monitoring firm in taking and analyzing air samples will be paid for by DEP.



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: untitled

05/20/02 PUBLIC ACCESS PROPERTY PROFILE OVERVIEW BISPIQ
 128..... CHAMBERS STREET..... 1 MANHATTAN 10007 BIN# 10014

CHAMBERS STREET 128 - 132 HEALTH AREA : 77 TAX BLK: 136
 WEST BROADWAY 85 - 93 CENSUS TRACT: 21 TAX LOT: 16.
 COMMUNITY BD: 101 CONDO :
 MULTI STRUCT: 01 VACANT :

=====

DOB SPECIAL PLACE NAME :	1	PROPERTY RECORD(
DOB BUILDING REMARKS :		
FINANCE OCCUPANCY CODE : K2-STORE BUILDING	LANDMARK STATUS:	

COUNTS FOR THIS BIN				RECORD VERIFIED : N
ACTIONS	: 13	, 10	JOBS/FILINGS (PF4)	SPECIAL STATUS :
VIOLATIONS DOB	: 13	, 0	OPEN	LOCAL LAW : N
ECB	: 4	, 1	OPEN (PF12)	SRO : N
COMPLAINTS	: 4	, 0	OPEN (PF11)	

PF 3 = ELEVATORS	ENTER KEY= ACTIONS	PF 5/6/7 = NEW ADDR/BIN/BLK-LOT
PF 8 = BOILERS	(TYPE :)	PF 9/10 = BROWSE BIN/BLK-LOT
*NO ARA'S FILED		PF 15 = BROWSE 1 PROPERTY RECOR
PF 14 = LPC/HPD/LOFT USE ONLY		PF 16 = ADDTN'L PROPERTY INFO

Date: 5/20/2002 Time: 02:58:36 PM