

Asbestos Inspection Report

Premise No. 90 FULTON STREET					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 77	Lot 23	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken (Yes/No)
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
THURSDAY SEPTEMBER 26 2002						
THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN TODAY. THE CLEAN UP OF THE ROOF OF THE ADJACENT PREMISE WAS CONDUCTED SIMULTANEOUSLY (92 FULTON STREET). FOR THE PURPOSES OF AIR SAMPLING THE ROOF AREAS OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE (CERTIFICATE # AH 01-01030 EXP 01/03)						
FRIDAY SEPTEMBER 27 2002						
THE CLEAN UP OF THE ROOF OF THE PREMISE AND THE ADJACENT PREMISE (92 FULTON STREET) WAS COMPLETED TODAY. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE. THE CLEAN UP OF THE REAR (SOUTH) FACADES WAS PERFORMED TODAY. AIR SAMPLING FOR THE REAR FACADE CLEAN UP WAS PERFORMED BY JERSON GARCIA (CERTIFICATE # AH-01-11633 EXP 03/03) OF WARREN & PANZER.						
SATURDAY SEPTEMBER 28 2002						
THE CLEAN UP OF THE SET BACK ROOF AREAS OF 92 FULTON AND 90 FULTON WERE CONDUCTED. FOR THE PURPOSES OF AIR SAMPLING THE SET BACK AREAS OF BOTH BUILDINGS WERE TREATED AS ONE WORK AREA. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE AND IDRIS (DOWNY) (CERTIFICATE # AH 02-11201 EXP 05/03)						
SUNDAY SEPTEMBER 29 2002						
THE CLEAN UP OF THE NORTH (FRONT) FACADE OF THE PREMISE AND THE ADJACENT PREMISE (92 FULTON ST) WAS CONDUCTED. A BOOM TRUCK WAS USED TO ACCESS FACADE SURFACES. A DECON TRUCK WAS UTILIZED. A PLASTIC DYKE WAS CONSTRUCTED TO COLLECT WATER RUN OFF. AIR SAMPLING WAS PERFORMED BY FESTY OSEMWEGIE. AIR SAMPLES WERE SET UP ON THE OPPOSITE SIDEWALK. ALL CLEANED WORK AREAS WERE INSPECTED AND NO VISIBLE WTC DEBRIS WAS OBSERVED. THE CLEAN UP PROJECT IS NOW COMPLETE						

pl.