

## Asbestos Inspection Report

|                                                                                                                                                                                                                                                                                                                                                                                             |              |                            |             |                                      |                              |                           |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------|----------------------------|-------------|--------------------------------------|------------------------------|---------------------------|
| Premise No.<br>92 FULTON STREET                                                                                                                                                                                                                                                                                                                                                             |              |                            |             |                                      | Inspection Date:<br>AS NOTED |                           |
| Floor<br>ROOF & FACADE                                                                                                                                                                                                                                                                                                                                                                      | Zip<br>10038 | Borough<br>1               | Block<br>77 | Lot<br>22                            | Squad #<br>N/A               | Badge #<br>A020           |
| Inspector<br>Dennis Antzoulatos                                                                                                                                                                                                                                                                                                                                                             |              | Building Type<br>MIXED USE |             | Basis of Inspection<br>WTC Survey    |                              | Photos Taken<br>(Yes/ No) |
| Contractor's Name<br>Benjamin Kurzbau & Son Control                                                                                                                                                                                                                                                                                                                                         |              |                            |             | Sample Number<br>N/A                 |                              |                           |
| Address City<br>1248 Ralph Avenue, Brooklyn                                                                                                                                                                                                                                                                                                                                                 |              |                            |             | Sample Number<br>N/A                 |                              |                           |
| State Zip Phone<br>NY 11236 (718)531-2900                                                                                                                                                                                                                                                                                                                                                   |              |                            |             | Sample Number<br>N/A                 |                              |                           |
| Laboratory Name<br>Warren & Panzer Engineers Inc.                                                                                                                                                                                                                                                                                                                                           |              |                            |             | Owner's Name                         |                              |                           |
| Address City<br>228 East 45 Street New York                                                                                                                                                                                                                                                                                                                                                 |              |                            |             | Address City                         |                              |                           |
| State Zip Phone<br>NY 10017 (212) 922-0077                                                                                                                                                                                                                                                                                                                                                  |              |                            |             | State Zip Phone                      |                              |                           |
| Contact Person                                                                                                                                                                                                                                                                                                                                                                              |              |                            |             | Time of Inspection from:<br>AS NOTED |                              |                           |
| THURSDAY SEPTEMBER 26, 2002                                                                                                                                                                                                                                                                                                                                                                 |              |                            |             |                                      |                              |                           |
| THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN TODAY. THE CLEAN UP OF THE ROOF OF THE ADJACENT PREMISE WAS CONDUCTED SIMULTANEOUSLY (90 FULTON STREET). FOR THE PURPOSES OF AIR SAMPLING THE ROOF AREAS OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA. AIR SAMPLING FOR TODAY'S CLEAN UP ACTIVITIES WAS PERFORMED BY FESTY OSEMWEGIE (CERTIFICATE # AH 01-01030 EXP 01/03)            |              |                            |             |                                      |                              |                           |
| FRIDAY SEPTEMBER 27, 2002                                                                                                                                                                                                                                                                                                                                                                   |              |                            |             |                                      |                              |                           |
| THE CLEAN UP OF THE ROOF OF THE PREMISE AND THE ADJACENT PREMISE (90 FULTON STREET) WAS COMPLETED TODAY. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE. THE CLEAN UP OF THE REAR (SOUTH) FACADE WAS PERFORMED TODAY. AIR SAMPLING FOR THE REAR FACADE CLEAN UP WAS PERFORMED BY JESRON GARCIA (CERTIFICATE # AH 01-11633 EXP 03/03) OF WARREN & PANZER.    |              |                            |             |                                      |                              |                           |
| SATURDAY SEPTEMBER 28 2002                                                                                                                                                                                                                                                                                                                                                                  |              |                            |             |                                      |                              |                           |
| THE CLEAN OF THE SET BACK ROOF AREAS OF 92 FULTON AND 90 FULTON WERE CONDUCTED. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP PROJECT WAS PERFORMED BY FESTY OSEMWEGIE AND IDRIS IDOWINY (CERTIFICATE # AH 02-11201 EXP 05/03)                                                                                                                                                              |              |                            |             |                                      |                              |                           |
| SUNDAY SEPTEMBER 29 2002                                                                                                                                                                                                                                                                                                                                                                    |              |                            |             |                                      |                              |                           |
| THE CLEAN UP OF THE NORTH (FRONT) FACADE OF THE PREMISE WAS CONDUCTED. A BOOM TRUCK WAS USED TO ACCESS FACADE SURFACES. A DECON TRUCK WAS UTILIZED. A PLASTIC DYKE WAS CONSTRUCTED TO COLLECT WATER RUN OFF. AIR SAMPLING WAS PERFORMED BY FESTY OSEMWEGIE. AIR SAMPLES WERE SET UP ON THE OPPOSITE SIDEWALK. ALL CLEANED WORK AREAS WERE INSPECTED AND NO VISIBLE WTC DEBRIS WAS OBSERVED. |              |                            |             |                                      |                              |                           |

22