

WTC Visual Survey Form

1001190

Premise Address: <u>92 Fulton St</u>		
Block: <u>33</u>	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:**Facade:**

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Still dirty broken windows etc. facades and windows are

Roof

Debris: ☐ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.

Description: _____

Setbacks ☐ N/A

Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	Debris: ☐ ½ to 1"	Debris: ☐ > 1"

Comments

No Access into bldg

Date: 3/12/2002Inspection Team: Name: AL

Agency: _____

Name: _____

Agency: _____