

**BENJAMIN KURZBAN
& SON CONTROL, INC.**1248 Ralph Ave.
BROOKLYN, N.Y. 11236**INVOICE****1221****(718) 531-2900**

TO

Dept of Environmental Protection

59-17 Junction Blvd

Corona, NY 11368

DATE 11/7/02	ORDER NO.
SHIP TO Contract ROF-REM2	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS
QUANTITY	DESCRIPTION	UNIT PRICE	TOTAL	
>	Registration # CT 82620020015280			
	Pin# 82602WTCROOF2			
	For work completed at 94 Fulton St			
	20,000 SF @ 2/SF			
	Total Amount due this Invoice			\$40,000.00
	<i>R. Rader</i>			

ORIGINAL


Thank You!

E. 204 WTC



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program

59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107
ASBESTOS PROJECT NOTIFICATION
 (ASBESTOS INSPECTION REPORT)

 1. NYC DEP
 (See fee schedule)

EMERGENCY
Janet

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 94 FULTON STREET Borough MAN Zip 10038
 AKA _____ 3. Block _____ 4. Lot _____
 5. Type of Facility MIXED USE 6. Name of Building _____

II. BUILDING OWNER

7. Name _____ 8. Contact Person _____
 9. Tel. # _____ Fax # _____
 10. Address _____ City _____ State _____ Zip _____

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KURZBAN & SON CONTROL INC 13. Contact Person LOUIE IANNICO
 14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
 16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN
 19. Federal Employer ID. # PII 20. Tel. # (212) 922-0077 Fax # (212) 922-0630
 21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
 22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 10/21/02 Projected completion date 11/21/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday


Shift from: 8 ☒ am ☐ pm to 8 ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

20,000 Square Feet, and/or 0 Linear Feet


 ACP 7
 2/2001

 DEP
 BUREAU OF ENVIRONMENTAL
 REMEDIATION & ENFORCEMENT
 ASBESTOS CONTROL
 PROGRAM
 TRU 1

ASBESTOS INSPECTION REPORT (continued)26. Asbestos Hauler IESI, NY NYS DEC Permit # NJ-462 Tel.# (718) 522-2263Disposal Site(s) BLUERIDGE LANDFILL PO BOX 399 SCOTSDALE PA 17254

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
 e) ☐ Fireproofing Replacement f) ☐ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up


29. ABATEMENT PROCEDURE (Check all appropriate boxes)

- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application

30. LOCATIONS OF ABATEMENT

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET	DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
ROOF		ROOF SURFACES	2645	INCLUDES SKYLIGHTS
II		A/C UNITS & METAL	800	
SET BACK ROOF	(2ND FLOOR)	ROOF SURFACE	1890	
II		A/C UNITS & METAL	5000	
FACADE	NORTH	FACADE SURFACE	2755	
II	II	FIRE ESCAPES	4000	
II	II	STORE ALUNING	500	
FACADE	SOUTH	FACADE SURFACE	300	PARTIAL
FACADE	WEST	FACADE SURFACE	1500	PARTIAL
FACADE	EAST	FACADE SURFACE	610	

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

WARREN & PANZER ENGINEERS Print Name of Air Monitor  Signature 10/17/02 Date	B. KURZBAN & SON CONTROL INC. Print Name of Asbestos Contractor  Signature 10/17/02 Date	_____ Print Name of Applicant (If other than Owner) _____ Signature _____ Date
---	--	---

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

Print Name of Owner

Signature

Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.

Asbestos Inspection Report

Premise No. 94 FULTON STREET					Inspection Date: As NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 77	Lot 21	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken Yes/ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: As NOTED		

MONDAY OCTOBER 21 2002

CONTRACTOR BRINGS MATERIALS AND EQUIPMENT TO THE JOBSITE. THE GFI ELECTRICAL PANEL IS SET UP.

TUESDAY OCTOBER 22 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY CELESTINE NMORIK (CERTIFICATE # AH 02-08495 EXP 04/03).

WEDNESDAY OCTOBER 23 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE CONTINUES. THE CLEAN UP OF THE SETBACK ROOF AREA BEGAN. AIR SAMPLING WAS PERFORMED BY YURI BEDIN (CERTIFICATE # AH 96-14947 EXP 02/03) OF WARREN & PANZER.

THURSDAY OCTOBER 24 2002

THE CLEAN UP OF THE ROOF AND SETBACK AREAS WAS COMPLETED. AIR SAMPLING WAS PERFORMED BY YURI BEDIN. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED WORK AREAS AND I OBSERVED NO VISIBLE WTC DEBRIS.

SUNDAY OCTOBER 28 2002 (700AM - 200PM)

THE CLEAN UP OF THE NORTH FACADE OF THE PREMISE WAS CONDUCTED. AIR SAMPLING WAS PERFORMED BY WIS GOTO (CERTIFICATE # PII EXP 03/03). DUE TO THE DELI OWNER'S REFUSAL TO CLOSE THE CLEAN UP PROCEDURES AT THE PREMISE HAD TO BE CHANGED. FACADE SURFACES WERE WET WIPED AND HEPA VACUUMED INSTEAD OF BEING HEPA VACUUMED AND POWER WASHED. THE REFRIGERATOR UNIT OUTSIDE THE DELI (LOCATED ON THE SIDE WALK) WAS COVERED WITH TWO LAYERS OF PLASTIC AND LEFT IN PLACE. SEVERAL DELI PATRONS CROSSED CAUTION TAPE AND

Asbestos Inspection Report

Premise No. <u>94 FULTON STREET</u>	Inspection Date: <u>AS NOTED</u>
Inspector <u>Dennis Antzoulatos</u>	Page <u>2</u> of <u>2</u>

SIDEWALK CLOSURE BARRIERS DURING THE CLEAN UP PROCEDURES TO GAIN
 ACCESS INTO THE DELI DESPITE THE CLEAN UP CONTRACTORS AND DEP'S
 EFFORTS TO PREVENT SUCH ACTION. DELI EMPLOYEES WERE REPEATEDLY ASKED
 TO KEEP THE DELI'S DOOR CLOSED DURING THE CLEAN UP. ON SEVERAL
 OCCASIONS DELI EMPLOYEES WERE ASKED EITHER TO REMAIN INSIDE THE DELI
 OR EXIT THE CORDONED OFF SIDE WALK AREA UPON LEAVING THE DELI (EMPLOYEES
 WOULD EXIT THE DELI AND REMAIN IN THE CLOSED SIDE WALK AREA TO OBSERVE THE WORK).
 AS A RESULT, THE CLEAN UP TIME FOR THIS FACADE CLEAN UP WAS GREATLY
 INCREASED. UPON COMPLETION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL
 INSPECTION OF CLEANED FACADE SURFACES AND FIRE ESCAPE. BULK WTC
 DEBRIS MATERIAL WAS REMOVED FROM ALL SURFACES. FINE LAYERS OF DEBRIS
 FROM THE FIRE ESCAPE AND AWNING REMAINED OR PROVED UNACCESSABLE WITHOUT
 POWER WASHING. THE FACADE CLEAN UP WAS DEEMED ACCEPTABLE TO THE DEPARTMENT
 UNDER THE CIRCUMSTANCES. THE CLEAN UP AT THE PREMISE IS NOW COMPLETE.