

Asbestos Inspection Report

Premise No. 94 FULTON STREET					Inspection Date: As NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 77	Lot 21	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type MIXED USE		Basis of Inspection WTC Survey		Photos Taken Yes/ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: As NOTED		

MONDAY OCTOBER 21 2002

CONTRACTOR BRINGS MATERIALS AND EQUIPMENT TO THE JOBSITE. THE GFI ELECTRICAL PANEL IS SET UP.

TUESDAY OCTOBER 22 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY CELESTINE NMORKA (CERTIFICATE # AH 02-08495 EXP 04/03).

WEDNESDAY OCTOBER 23 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE CONTINUES. THE CLEAN UP OF THE SET BACK ROOF AREA BEGAN. AIR SAMPLING WAS PERFORMED BY YURI BEDIN (CERTIFICATE # AH 96-14947 EXP 02/03) OF WARREN & PANZER.

THURSDAY OCTOBER 24 2002

THE CLEAN UP OF THE ROOF AND SETBACK AREAS WAS COMPLETED. AIR SAMPLING WAS PERFORMED BY YURI BEDIN. AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED WORK AREAS AND I OBSERVED NO VISIBLE WTC DEBRIS.

SUNDAY OCTOBER 28 2002 (100AM - 200PM)

THE CLEAN UP OF THE NORTH FACADE OF THE PREMISE WAS CONDUCTED. AIR SAMPLING WAS PERFORMED BY WIS SOTO (CERTIFICATE # P11 EXP 03/03). DUE TO THE DELI OWNER'S REFUSAL TO CLOSE THE CLEAN UP PROCEDURES AT THE PREMISE HAD TO BE CHANGED. FACADE SURFACES WERE WET WIPED AND HEPA VACUUMED INSTEAD OF BEING HEPA VACUUMED AND POWER WASHED. THE REFRIGERATOR UNIT OUTSIDE THE DELI (LOCATED ON THE SIDE WALK) WAS COVERED WITH TWO LAYERS OF PLASTIC AND LEFT IN PLACE. SEVERAL DELI PATRONS CROSSED CAUTION TAPE AND

Asbestos Inspection Report

Premise No. <u>94 FULTON STREET</u>	Inspection Date: <u>AS NOTED</u>
Inspector <u>Dennis Antzoulatos</u>	Page <u>2</u> of <u>2</u>

SIDEWALK CLOSURE BARRIERS DURING THE CLEAN UP PROCEDURES TO GAIN
 ACCESS INTO THE DELI DESPITE THE CLEAN UP CONTRACTORS AND DEP'S
 EFFORTS TO PREVENT SUCH ACTION. DELI EMPLOYEES WERE REPEATEDLY ASKED
 TO KEEP THE DELI'S DOOR CLOSED DURING THE CLEAN UP. ON SEVERAL
 OCCASSIONS DELI EMPLOYEES WERE ASKED EITHER TO REMAIN INSIDE THE DELI
 OR EXIT THE CORDONED OFF SIDE WALK AREA UPON LEAVING THE DELI (EMPLOYEES
 WOULD EXIT THE DELI AND REMAIN IN THE CLOSED SIDE WALK AREA TO OBSERVE THE WORK).
 AS A RESULT, THE CLEAN UP TIME FOR THIS FACADE CLEAN UP WAS GREATLY
 INCREASED. UPON COMPLETION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL
 INSPECTION OF CLEANED FACADE SURFACES AND FIRE ESCAPE. BULK WTC
 DEBRIS MATERIAL WAS REMOVED FROM ALL SURFACES. FINE LAYERS OF DEBRIS
 FROM THE FIRE ESCAPE AND AWNING REMAINED OR PROVED UNACCESSABLE WITHOUT
 POWER WASHING. THE FACADE CLEAN UP WAS DEEMED ACCEPTABLE TO THE DEPARTMENT
 UNDER THE CIRCUMSTANCES. THE CLEAN UP AT THE PREMISE IS NOW COMPLETE.