

Asbestos Inspection Report

Premise No. 125 FULTON STREET					Inspection Date: AS NOTED	
Floor ROOF AND FACADE	Zip	Borough 1	Block 91	Lot 10	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken Yes ☒ No ☐
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
FRIDAY JUNE 21 2002						
8:00AM WORKERS BEGIN THE ROOF CLEAN UP AT THIS PREMISE. AIR SAMPLING FOR THIS WORK WILL BE PERFORMED BY JOHN BOYD OF WARREN & PANZER ENGINEERS.						
6:00PM THE ROOF CLEAN UP AT THIS PREMISE IS NOW COMPLETE. A VISUAL INSPECTION IS CONDUCTED AT THIS TIME. NO VISIBLE WTC DEBRIS WAS OBSERVED.						
SUNDAY JUNE 23, 2002						
6:00 PM WORKERS BEGIN THE FACADE CLEAN UP (SOUTH FACADE - FULTON STREET) THE FACADE CLEAN-UP OF 123 FULTON STREET IS ALSO BEING DONE. FOR THE PURPOSES OF AIR MONITORING, THE FACADES OF THESE TWO BUILDINGS ARE BEING TREATED AS ONE WORK AREA. LARRY BAER OF WARREN & PANZER PERFORMS THE AIR SAMPLING.						
8:00PM FACADE CLEAN UP IS NOW COMPLETE. GREG FRUCHTMAN (NYC DEP) AND I PERFORM A VISUAL INSPECTION OF THE FACADE AND OBSERVE NO VISIBLE WTC DEBRIS.						

WTC Visual Survey Form

Premise Address:			125 FULTON STREET		
Block:	91	Residential	☐	Commercial	☒
Lot:	10	Mix Use	☐	Other	☐
# of Stories:		AKA's:			
Building Owner/Management:			Telephone Number: (718) 726-7700		
Name: GRECIAN MANAGEMENT INC			FAX: ()		
Address: 22-29 28TH ST ASTORIA NY 11105					
On Site Contact:			Telephone Number: ()		
Building Owner Management Activities					
Interior Survey Performed ☐ Yes ☐ No					
Exterior Survey Performed ☐ Yes ☐ No					
General Clean Up ☐ Yes ☐ No Locations: _____					
ACM Clean Up ☐ Yes ☐ No Locations: _____					
Air Monitoring ☐ Yes ☐ No Locations: _____					
Copies of All Reports and Data Requested ☐ Yes					

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1"	☐ > 1"
East	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
DEBRIS ON WINDOW LEDGES					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description:					
DEBRIS ON PARAPET					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer		☐ ½ to 1"	☐ > 1"	
Comments					

Date: 06 / 10 /2002

Inspection Team: Name: DA / A020

Agency: NYC DEP
Agency: _____