

**BENJAMIN KURZBAN
& SON CONTROL, INC.**
248 Ralph Ave.
BROOKLYN, N.Y. 11236

(718) 531-2900

INVOICE

1204

TO

Dept of Environmental Protection

59-17 Junction Blvd

Corona, NY 11368

DATE 10/15/02	ORDER NO.
SHIP TO Contract ROM-REF2	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	CO. POINT	TERMS
QUANTITY	DESCRIPTION	UNIT PRICE	TOTAL	
>	Registration # CT 82620020015280			
	Pin# 82602WTCROOF2			
	For work completed at 141 Fulton St			
	12,980 SF @ 2/SF			
	Total Amount due this Invoice		\$25,960.00	
	<i>R. Raeh</i>			

ORIGINAL

Thank You!

22. Sample Analysis Laboratory _____ 23. NTS CORRELATION # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work _____ Projected completion date _____

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday

Shift from: 8 ☒ am ☐ pm to 8 ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

12980 Square Feet, and/or 0 Linear Feet

BUREAU OF ENVIRONMENTAL
REMEDIAL ACTION & ENFORCEMENT
ASBESTOS CONTROL
PROGRAM
TRU 2

ACP 7
2/2001

E185WTC

ONLY
EMERGENCY
FOR USE ONLY
ACCEPTED

NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

TRU1617MN02
Building Dept. or TRU No
FOR OFFICIAL USE ONLY
1. NYC DEP
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 141 FULTON STREET Borough MN Zip _____
AKA _____ 3. Block 89 4. Lot 2
5. Type of Facility MIXED USE 6. Name of Building _____

II. BUILDING OWNER

7. Name _____ 8. Contact Person _____
9. Tel. # _____ Fax # _____
10. Address _____ City _____ State _____ Zip _____

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KURZBAN & SON CONTROL 13. Contact Person LEVIE IANNICO
14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # PII 20. Tel. # (212) 922-0011 Fax # (212) 922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 9/29/02 Projected completion date 10/7/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday

Shift from: 8 ☒ am ☐ pm to 8 ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

12980 Square Feet, and/or 0 Linear Feet



ACP 7
2/2001

BUREAU OF ENVIRONMENTAL
REGULATION & CONSTRUCTION
ASBESTOS CONTROL
PROGRAM
TRU 2

ASBESTOS INSPECTION REPORT (continued)

26. Asbestos Hauler IESI, NY NYS DEC Permit # NJ-462 Tel.# (718) 522-2263
 Disposal Site(s) BLUERIDGE LANDFILL PO BOX 399 SCOTSDALE PA 17254

27. This asbestos abatement is part of a (Item a through e requires filing of this form with NYC Department of Buildings)

- a) ☐ Demolition b) ☐ Boiler Replacement c) ☐ Sprinkler Replacement d) ☐ Renovation/Alteration
 e) ☐ Fireproofing Replacement f) ☐ Other (Describe) _____

28. TYPE OF ABATEMENT (Check all appropriate boxes)

- ☐ Removal ☐ Enclosure ☐ Encapsulation ☐ Repair ☒ Clean up


29. ABATEMENT PROCEDURE (Check all appropriate boxes)

- ☐ Full Containment ☐ Glovebag ☐ Tent ☐ DEP Variance Application


30. LOCATIONS OF ABATEMENT**ROOF MATERIAL: ROOF MEMBRANE**

Floor(s)	DESCRIBE SECTION OF FLOOR (e.g. entire, east wing, room #, boiler room, lobby, etc.)	AFFECTED SURFACES CONTAINING ACM (e.g. Pipe lagging, ceiling, plenum ducts, storage tanks, decking, etc.)	AMOUNT OF ACM SQUARE FEET LINEAR FEET	DESCRIPTION OF WORK BEING PERFORMED (e.g. running cable, installing fire sprinklers, removing and replacing boilers, etc.)
ROOF		ROOF SURFACE	2100	
"		A/C UNITS & METAL	3000	
"		VERTICAL DUCTS	2500	
FACADE	SOUTH FACADE	FACADE SURFACES	910	
"	NORTH FACADE	FACADE SURFACES	2170	
"		BALCONIES & FENCES	600	
SET BACK	TOP SET BACK	ROOF SURFACE	128	
"	"	METAL SURFACES	700	
"	BOTTOM SET BACK	BLACK SINGLE ROOF	286	
"	"	CONCRETE ROOF	286	

31. I hereby declare that the information provided herein is true and complete to the best of my knowledge. I am familiar with Federal, State and NYC laws and regulations applicable to asbestos related work.

WARREN & PANZER ENGINEERS Print Name of Air Monitor  Signature <u>07-26-02</u> Date	B. KURZBAN & SON CONTROL Print Name of Asbestos Contractor  Signature <u>07-26-02</u> Date	_____ Print Name of Applicant (If other than Owner) _____ Signature _____ Date
--	--	---

32. I understand that as the owner of a building where asbestos abatement activity occurs, I am responsible for the performance of the asbestos abatement activities in accordance with the Asbestos Control Program Rules. I have contracted the third party air monitor who is completely independent of all parties involved in the asbestos project. I hereby declare that I have authorized the filing of this notification for the work specified herein.

 Print Name of Owner  NYC DEP 07-26-02
 Signature Date

A STAMPED COPY OF THIS FORM INCLUDING AMENDMENTS MUST BE AVAILABLE AT THE WORK SITE.

Any modification of information provided on this form must be reported immediately in writing directly to the NYC DEP ACP.

The requirements of the Asbestos Control Program Rules may not be lawfully avoided or lessened through the performance of work in incremental or piecemeal fashion.



Athenica

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7490
Fax. (718) 784-4055

CLIENT: Warren & Panzer Engineers, P.C.
LABORATORY ID #: T02-09-117
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.E.
AVERAGE G.O. AREA (mm²): 0.013838

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

PROJECT: NYC DEP, 141 Fulton Street
DATE OF REPORT: 09/30/02
DATE OF ANALYSIS: 09/30/02
EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (fug./cm ³)	TOTAL ASBESTOS AIR CONC. (fug./cm ³)	TOTAL ASBESTOS FILTER CONC. (fug./mm ²)	AIR CONC. FOR STRUCT. 0.4-8.0µm	AIR CONC. FOR STRUCT. >8.0µm	ASBEST. TYPE CHERYS.	ANALYT. ASBEST. TYPE SPECIFY
ID01	T02-09-117-2675	IWA left side of WA (roof)	1440	4	0.0554	0.0048	<0.0048	<18.07	NA	NA	NA	NA
ID02	T02-09-117-2676	IWA 1 st middle of WA (roof)	1440	4	0.0554	0.0048	<0.0048	<18.07	NA	NA	NA	NA
ID03	T02-09-117-2677	IWA 2 nd middle of WA (roof)	1440	4	0.0554	0.0048	<0.0048	<18.07	NA	NA	NA	NA
ID04	T02-09-117-2678	IWA right side of WA (roof)	1440	4	0.0554	0.0048	<0.0048	<18.07	NA	NA	NA	NA
ID05	T02-09-117-2679	Exit to the roof	1440	4	0.0554	0.0048	<0.0048	<18.07	NA	NA	NA	NA

C. Siakou

ANALYST
E. Sioukri

[Signature]

LABORATORY DIRECTOR
Spiro Dougaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a base duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.



ATHENICA

ENVIRONMENTAL SERVICES
Tel. (718) 744-7490
Fax. (718) 744-1095

CLIENT: Warren & Panzer Engineers, P.C.

LABORATORY ID #: T02-10-005

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

AVERAGE G.O. AREA (mm²): 0.01838

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

PROJECT: NYCDEP, 141 Fulton Street, NY

DATE OF REPORT: 10/01/02

DATE OF ANALYSIS: 10/01/02

EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (M)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (microg/cm ³)	TOTAL ASBESTOS AIR CONC. (microg/cm ³)	TOTAL ASBESTOS FILTER CONC. (microg/cm ³)	AIR CONC. FOR 0.55-5.0 micron	AIR CONC. FOR 5.0-10.0 micron	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
1	T02-10-005-2705	IWA on roof. Center of work area	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA
2	T02-10-005-2706	IWA on roof. North section of WA	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA
3	T02-10-005-2707	IWA on roof. 4ft of door entrance of roof	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA
4	T02-10-005-2708	OWA on roof. Inside clean room of Decon	1800	4	0.0554	0.0039	0.0077	36.13	<0.0039	0.0077	Chrys.	NA
5	T02-10-005-2709	OWA 3ft of door entrance on stairwell leading to roof	1800	4	0.0554	0.0039	<0.0039	<18.07	NA	NA	NA	NA

ANALYST
B. Sioukri

LABORATORY DIRECTOR
Spiro Dongaris

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a new duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**220 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-8630**

WARREN & PANZER ENGINEERS, P. C.
MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

Fax (212) 922-8630

	24 hr ⁺ /a	12 hr ⁺ /a	6 hr ⁺ /a	3 hr ⁺ /a	Immediate ⁺ /a
1	100	100	100	100	100
2	100	100	100	100	100
3	100	100	100	100	100
4	100	100	100	100	100
5	100	100	100	100	100
6	100	100	100	100	100
7	100	100	100	100	100
8	100	100	100	100	100
9	100	100	100	100	100
10	100	100	100	100	100
11	100	100	100	100	100
12	100	100	100	100	100
13	100	100	100	100	100
14	100	100	100	100	100
15	100	100	100	100	100
16	100	100	100	100	100
17	100	100	100	100	100
18	100	100	100	100	100
19	100	100	100	100	100
20	100	100	100	100	100
21	100	100	100	100	100
22	100	100	100	100	100
23	100	100	100	100	100
24	100	100	100	100	100
25	100	100	100	100	100
26	100	100	100	100	100
27	100	100	100	100	100
28	100	100	100	100	100
29	100	100	100	100	100
30	100	100	100	100	100
31	100	100	100	100	100
32	100	100	100	100	100
33	100	100	100	100	100
34	100	100	100	100	100
35	100	100	100	100	100
36	100	100	100	100	100
37	100	100	100	100	100
38	100	100	100	100	100
39	100	100	100	100	100
40	100	100	100	100	100
41	100	100	100	100	100
42	100	100	100	100	100
43	100	100	100	100	100
44	100	100	100	100	100
45	100	100	100	100	100
46	100	100	100	100	100
47	100	100	100	100	100
48	100	100	100	100	100
49	100	100	100	100	100
50	100	100	100	100	100
51	100	100	100	100	100
52	100	100	100	100	100
53	100	100	100	100	100
54	100	100	100	100	100
55	100	100	100	100	100
56	100	100	100	100	100
57	100	100	100	100	100
58	100	100	100	100	100
59	100	100	100	100	100
60	100	100	100	100	100
61	100	100	100	100	100
62	100	100	100	100	100
63	100	100	100	100	100
64	100	100	100	100	100
65	100	100	100	100	100
66	100	100	100	100	100
67	100	100	100	1	

CLIENT: DER.

W&P FILE #: 1079.01.02

LABORATORY: Warren and P
PROJECT: DEP Sampling Project

LOCATION: 141 Eubank St., NY. NY.

7400 AHERA EPA LEVEL II

TECHNICIAN: Jury Bedin.

SAMPLE	PUMP	FLOWRATE
--------	------	----------

[illegible]

COMMENTS

SAMPLE BY: Yury Bedin DATE: 9-30-02

SIGNATURE: Christ Brackin

RELEASED BY: Yury! Bed.n. DATE: 9-30-02

SIGNATURE: Yun Yadi Released - 20:03

RECEIVED BY: E. S. S. 11/1/08 DATE: 10/1/08

SIGNATURE: _____

T02-10-005

SAMPLE TYPE CODES

1 - Blank	5 - Final Clean
-----------	-----------------

2 - Pre-Abatement

3 - During Abatement

SEE REVERSE SIDE FOR ANALYSIS INFORMATION


ATHENICA

ENVIRONMENTAL SERVICES INC.

 Tel. (718) 784-7990
 Fax. (718) 784-4085

 CLIENT: Warren & Panzer Engineers, P.C.
 LABORATORY ID #: T02-10-010
 ANALYT. METHODOLOGY: AHERA
 FILTER TYPE: M.C.E.
 AVERAGE G.O. AREA (mm²): 0.013838

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

 PROJECT: NYCDER, 141 Fulton St.
 DATE OF REPORT: 10/02/02
 DATE OF ANALYSIS: 10/02/02
 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (l)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIV. (struct./cm ³)	TOTAL ASBESTOS AIR CONC. (struct./cm ³)	TOTAL ASBESTOS FILTER CONC. (struct./cm ³)	AIR CONC. FOR STRUCT. 0.55-5µm	AIR CONC. FOR STRUCT. 0.25-0.4µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
1	T02-10-010-2730	On roof. Center of work area.	1560	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA
2	T02-10-010-2731	On roof. South section of W.A.	1560	4	0.0554	0.0045	0.0045	18.07	0.0045	<0.0045	Chrys.	NA
3	T02-10-010-2732	On roof. West section of W.A.	1560	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA
4	T02-10-010-2733	On roof. Inside clean room of decon.	1560	4	0.0554	0.0045	0.0090	36.14	0.0090	<0.0045	Chrys	NA
5	T02-10-010-2734	On the stairwell leading to roof 2ft of door entrance.	1560	4	0.0554	0.0045	<0.0045	<18.07	NA	NA	NA	NA

E. Sioukri
ANALYST
 E. Sioukri

LABORATORY DIRECTOR
 Spiro Dongadis

Spiro Dongadis
LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street
New York, NY 10017
(212) 922-8877
Fax (212) 922-0630**

CLIENT: **DEP.**

PROJECT: *SEF - Sampling Roof Cleaning.*
LOCATION: *141 Furber St. NY. NY.*
on the Roof

On The Roof

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr⁺/a **12 hr⁺/a** **6 hr⁺/a** **3 hr⁺/a** **Immediate ⁺/a**

W&P FILE #: 1079.01.02.

LABORATORY: Warren and Pover.

ANALYSIS METHOD: PCM
circle one / 7400 TEM TEM
AHERA EPA 1 EV

TECHNICIAN: Virgil R. R. R.

CONTACT: MR. M. Nolan.

PAGE 1 OF 1.

P.O.

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
1. I.W.A.	on Roof. Center of Wind Area.	3		3.0 3.0	8:40 17:20	520	1560	
2. I.W.A.	on Roof. South Section of W. A.	3		3.0 3.0	8:42 17:22	520	1560	
3. I.W.A.	on Roof. West Section of W. A.	3		3.0 3.0	8:44 17:24	520	1560	
4. O.W.A.	on Roof. Inside Cleanroom of D.D. 3	3		3.0 3.0	8:46 17:26	520	1560	
5. O.W.A.	on the Slo. ^{25 ft} of Dyeos Engr. well leading to Roof	3		3.0 3.0	8:48 17:28	520	1560	
6 —	Field Blank —	1						
7 —	Field Blank —	1						
8 —	S. Blank —	1						

COMMENTS: 702-10-050

DATE: 10-1-02.

SAMPLE BY: Yury Bedin
SIGNATURE: Yury Bedin.

DATE: 10-1-02

RELEASED BY: Vukob Bedin.
SIGNATURE: Vukob Bedin. Release

DATE: 10/2/02

RECEIVED BY: G. Siapin
SIGNATURE: [Signature]

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

10/08/2002 16:59 FAX

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7490

Fax. (718) 784-4085

CLIENT: Warren & Panzer Engineers, P.C.
 LABORATORY ID #: T02-10-037
 ANALYT. METHODOLOGY: AHERA
 FILTER TYPE: M.C.B.
 AVERAGE G.O. AREA (mm²): 0.013838

PROJECT: NYC DEP, 141-143 Fulton Street
 DATE OF REPORT: 10/06/02
 DATE OF ANALYSIS: 10/06/02
 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB ID #	LOCATION	VOLUME (l)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (structure/cm ²)	TOTAL ASBESTOS AIR CONC. (structure/cm ²)	TOTAL ASBESTOS FILTER CONC. (air/mm ²)	AIR CONC. FOR STRUCT. 0.153-5µm	AIR CONC. FOR STRUCT. ≥5.0µm	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
01	T02-10-037-2860	Deli Café sidewalk	1200	5	0.0692	0.0046	<0.0046	<14.45	NA	NA	NA	NA
02	T02-10-037-2861	In front of phone booth	1200	5	0.0692	0.0046	<0.0046	<14.45	NA	NA	NA	NA
03	T02-10-037-2862	In front of Popeye's	1200	5	0.0692	0.0046	<0.0046	<14.45	NA	NA	NA	NA
04	T02-10-037-2863	In front of Lucille R.	1200	5	0.0692	SAMPLE OVERLOADED WITH PARTICULATE MATERIAL RENDERING IT UNACCEPTABLE FOR ANALYSIS						NA
05	T02-10-037-2864	In front of Chow time	1200	5	0.0692	0.0046	<0.0046	<14.45	NA	NA	NA	NA

ANALYST
E. Sioukri

LABORATORY DIRECTOR
Spiro Douganis

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, FLAP 10955

- Athenica Environmental Services Inc. (AESI), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AESI Inc., should be notified within this time frame for a true duplicate analysis.
- If AESI Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AESI Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

10/08/2002 16:59 FAX

**2228 East 45th Street
New York, NY 10017
(212) 622-0077
Fax (212) 622-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate⁺/a

CLIENT: DEP

PROJECT: ROOFS / FACADE
LOCATION: 141 - 143 FULTON ST.

W&P FILE #: 1074-01-02

LABORATORY:

ANALYSIS METHOD: PCM
circle one 7400

~~TEM~~ TEM
BARRERA EPA LEVEL II

TEMP

LAHERA EPA LEVEL II

TECHNICIAN: EDWIN B. ELLIS JR.

PAGE _____ OF _____

P.O.

CONTACT:

COMMENTS:

T02-10-037

SAMPLE BY: <u>B. Ellis</u>	DATE: <u>10/1/62</u>
SIGNATURE: <u>Edwin B. Ellis</u>	
RELEASED BY: _____	DATE: _____
SIGNATURE: _____	
RECEIVED BY: <u>A. Ellis</u>	DATE: <u>10/1/62</u>
SIGNATURE: <u>[Signature]</u>	

DATE:

RELEASED BY:

SIGNATURE:

RECEIVED BY.

EIGENVALUE:

SAMPLE TYPE CODES

Blank

2 - Pre-Abatement

3 - During Abatement-

4 - During Glove Bag Removal

5 - Final Clearance (inside)

6 - Final Clearance (outside)

7 - Personal

8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

Asbestos Inspection Report

Premise No. 141 FULTON STREET					Inspection Date: AS NOTED	
Floor ROOF & FACADE	Zip 10038	Borough 1	Block 89	Lot 2	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken <u>Yes</u> / No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
SUNDAY SEPTEMBER 29 2002 (0800AM - 0600PM) THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN. A REMOTE DECONTAMINATION UNIT WAS ERECTED ON THE ROOF OF THE PREMISE. AIR SAMPLING FOR THE DAY'S CLEAN UP ACTIVITIES WAS PERFORMED BY IDRIS IDOWY (CERTIFICATE # AH 02-11201 EXP 05/03). FOUR AIR SAMPLES WERE RUN ON THE CLEAN PORTION OF THE ROOF AND ONE AIR SAMPLE WAS RUN IN THE STAIRWELL LEADING TO THE ROOF.						
MONDAY SEPTEMBER 30 2002 (0800AM - 0800PM) THE ROOF CLEAN UP IS COMPLETED. THE CLEAN UP OF THE NORTH (REAR) FACADE AND BALCONIES BEGAN TODAY. AIR SAMPLING FOR THE DAYS CLEAN UP ACTIVITIES WAS PERFORMED BY YURI BEDIN (CERTIFICATE # AH 96-14947 EXP 02/03).						
TUESDAY OCTOBER 1, 2002 (0800AM - 0600PM) THE CLEAN UP OF THE NORTH FACADE AND THE BALCONIES WAS COMPLETED. AIR SAMPLING WAS PERFORMED BY YURI BEDIN OF WARREN & PANZER. AT THE COMPLETION OF THE CLEAN UP ACTIVITIES, I CONDUCTED A VISUAL INSPECTION OF THE CLEANED ROOF AND FACADE SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS.						
SATURDAY OCTOBER 5 2002 (0600AM - 1100AM) THE CLEAN UP OF THE SOUTH FACADE OF THE PREMISE WAS CONDUCTED TODAY. THE CLEAN UP OF THE SOUTH FACADE OF THE ADJACENT PREMISE (143 FULTON ST) OCCURRED SIMULTANEOUSLY. FOR THE PURPOSES OF AIR SAMPLING, THE FACADES OF THESE TWO BUILDINGS WERE TREATED AS ONE WORK AREA. A BOOM TRUCK WAS USED TO ACCESS THE FACADE SURFACES. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY EDWIN ELLIS (CERTIFICATE # AH 00-00613 EXP 10/02). NO VISIBLE WTC DEBRIS WAS OBSERVED AT THE CONCLUSION OF THE CLEAN UP ACTIVITIES. THE CLEAN UP PROJECT IS NOW COMPLETE.						