

WTC Visual Survey Form

Premise Address: <u>141 FULTON ST.</u>			
Block:	Residential ☐ Commercial ☒	Name of Building: <u>Chow Time</u>	
Lot:	Mix Use ☐ Other ☐		
# of Stories: <u>6</u>	AKA's:		
Building Owner/Management:		Telephone Number: ()	
Name:		FAX: ()	
Address:			
On Site Contact:		Telephone Number: ()	
Name: <u>NONE</u>			
Building Owner Management Activities			
Interior Survey Performed ☐ Yes ☐ No			
Exterior Survey Performed ☐ Yes ☐ No			
General Clean Up ☐ Yes ☐ No		Locations: _____	
ACM Clean Up ☐ Yes ☐ No		Locations: _____	
Air Monitoring ☐ Yes ☐ No		Locations: _____	
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:			
North ☐ N/A	Inspected	Debris	
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
West ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: _____			

Roof			
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"			
Description: _____			

Setbacks ☐ N/A			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments <u>was able to walk up to Roof on my own</u>			

Date: 3/15/2002Inspection by: Name: CAR

Agency: _____

Name: _____

Agency: _____