

**BENJAMIN KURZBAN  
& SON CONTROL, INC.**1248 Ralph Ave.  
BROOKLYN, N.Y. 11236

(718) 531-2900

**INVOICE**

1200

TO

Dept of Environmental Protection

59-17 Junction Blvd

Corona, NY 11368

|                              |           |
|------------------------------|-----------|
| DATE<br>10/15/02             | ORDER NO. |
| SHIP TO<br>Contract ROM-REF2 |           |
|                              |           |
|                              |           |

| SALESPERSON | DATE SHIPPED                     | SHIPPED VIA | LOAD POINT | TERMS      |
|-------------|----------------------------------|-------------|------------|------------|
| QUANTITY    | DESCRIPTION                      | UNIT PRICE  | TOTAL      |            |
| >           | Registration # CT 82620020015280 |             |            |            |
|             | Pin# 82602WTCROOF2               |             |            |            |
|             | For work completed at 44 Gold St |             |            |            |
|             | 1620 SF @ 2/SF                   |             |            |            |
|             | Total Amount due this Invoice    |             |            | \$3,240.00 |
|             | <i>R. Kurzban</i>                |             |            |            |
|             |                                  |             |            |            |
|             |                                  |             |            |            |
|             |                                  |             |            |            |

ORIGINAL


Thank You!

22. Sample Analysis Laboratory \_\_\_\_\_

**VI. PROJECT INFORMATION**24. Starting date for this portion of work 9/27/02Projected completion date 9/27/02Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ SundayShift from: 8<sup>00</sup> ☒ am ☐ pm to 8<sup>00</sup> ☐ am ☒ pmIf other,  
specify \_\_\_\_\_

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work


1620 Square Feet, and/or 0 Linear FeetACP 7  
2/200BUREAU OF ENVIRONMENTAL  
CONSTRUCTION  
ASBESTOS ABATEMENT  
PROGRAM  
UNIT 1

E184.WTC



**NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION**  
**Asbestos Control Program**  
 59-17 Junction Boulevard, 8<sup>th</sup> Floor, Corona, NY 11368-5107

**ASBESTOS PROJECT NOTIFICATION**  
**(ASBESTOS INSPECTION REPORT)**



1. NYC DEP  
 (See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

**I. FACILITY**

2. Address 44 GOLD STREET Borough MN Zip \_\_\_\_\_  
 AKA \_\_\_\_\_ 3. Block 76 4. Lot 25  
 5. Type of Facility \_\_\_\_\_ 6. Name of Building \_\_\_\_\_

**II. BUILDING OWNER**

7. Name 44 COUNTRY ASSOCIATES 8. Contact Person \_\_\_\_\_  
 9. Tel. # (212) 797-6913 Fax # \_\_\_\_\_  
 10. Address \_\_\_\_\_ City \_\_\_\_\_ State \_\_\_\_\_ Zip \_\_\_\_\_

**III. GENERAL CONTRACTOR**

11. Name \_\_\_\_\_ Tel. # \_\_\_\_\_

**IV. ASBESTOS ABATEMENT CONTRACTOR**

12. Name BENJAMIN KURZBAN & SON CONTROL INC 13. Contact Person LOUIE IANNICO  
 14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808  
 16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

**V. THIRD PARTY AIR MONITOR**

17. Name WARDEN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN  
 19. Federal Employer ID. # PII 20. Tel. # (212) 922-6077 Fax # (212) 922-0630  
 21. Address 228 EAST 45TH STREET City NY State NY Zip 10017  
 22. Sample Analysis Laboratory \_\_\_\_\_ 23. NYS DOH ELAP # \_\_\_\_\_

**VI. PROJECT INFORMATION**

24. Starting date for this portion of work 9/27/02 Projected completion date 9/27/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday


Shift from: 8<sup>00</sup> ☒ am ☐ pm to 8<sup>00</sup> ☐ am ☒ pm

If other,  
 specify \_\_\_\_\_

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

1620 Square Feet, and/or 0 Linear Feet



BUREAU OF ENVIRONMENTAL  
 REMEDIATION & ENFORCEMENT  
 ASBESTOS CONTROL  
 PROGRAM  
 TRU 17

ACP 7  
 2/200




**ATHENICA**

ENVIRONMENTAL SERVICES INC.

Tel. (718) 784-7490

Fax. (718) 784-4885

**AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY**

CLIENT: Warren &amp; Panzer Engineers, P.C.

LABORATORY ID #: T02-09-105

ANALYT. METHODOLOGY: AHERA

FILTER TYPE: M.C.E.

 AVERAGE G.O. AREA (mm<sup>2</sup>): 0.013818

PROJECT: NYC DEP, 44 Gold St.

DATE OF REPORT: 09/28/02

DATE OF ANALYSIS: 09/28/02

 EFFECTIVE FILTER AREA (mm<sup>2</sup>): 385

**LABORATORY RESULTS**

| CLIENT # | LAB. ID #       | LOCATION                    | VOLUME (ft) | G.O. ANAL. YZED | AREA ANALYZED (mm <sup>2</sup> ) | ANALYT. SENSITIV. (struct./cm <sup>2</sup> ) | TOTAL ASBESTOS AIR CONC. (atmc./cm <sup>3</sup> ) | TOTAL ASBESTOS FILTER CONC. (atmc./mm <sup>2</sup> ) | AIR CONC. FOR STRUCT. ANALYSIS | AIR CONC. FOR STRUCT. ANALYSIS | ASBEST. TYPE CHRYS. | AMPHIB. ASBEST. TYPE SPECIFY |
|----------|-----------------|-----------------------------|-------------|-----------------|----------------------------------|----------------------------------------------|---------------------------------------------------|------------------------------------------------------|--------------------------------|--------------------------------|---------------------|------------------------------|
| 01       | T02-09-105-2609 | East side 44 Gold St. roof  | 1350        | 5               | 0.0692                           | 0.0041                                       | <0.0041                                           | <14.45                                               | NA                             | NA                             | NA                  | NA                           |
| 02       | T02-09-105-2610 | West side 44 Gold St. roof  | 1350        | 5               | 0.0692                           | 0.0041                                       | <0.0041                                           | <14.45                                               | NA                             | NA                             | NA                  | NA                           |
| 03       | T02-09-105-2611 | West side 44 Gold St. roof  | 1350        | 5               | 0.0692                           | 0.0041                                       | <0.0041                                           | <14.45                                               | NA                             | NA                             | NA                  | NA                           |
| 04       | T02-09-105-2612 | East side 44 Gold St. roof  | 1350        | 5               | 0.0692                           | 0.0041                                       | <0.0041                                           | <14.45                                               | NA                             | NA                             | NA                  | NA                           |
| 05       | T02-09-105-2613 | Inside 44 Gold St. roof adj | 1350        | 5               | 0.0692                           | 0.0041                                       | <0.0041                                           | <14.45                                               | NA                             | NA                             | NA                  | NA                           |

*E. Sioukri*
**ANALYST**

E. Sioukri

**LABORATORY DIRECTOR**

Spiro Dongaris

**LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955**

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to the material tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street  
New York, NY 10017  
(212) 922-0877  
Fax (212) 922-0630**

**WARREN & PANZER ENGINEERS, P. C.**  
**AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM**

**Fax (212) 922-0630**

24 hr<sup>+</sup>/a    12 hr<sup>+</sup>/a    6 hr<sup>+</sup>/a    3 hr<sup>+</sup>/a    Immediate<sup>+</sup>/a

**P.O.**

**CLIENT:**

DEP

**PROJECT:**

Confidential

**LOCATION:**

601/25

W&amp;P FILE #:

**LABORATORY:**

ANALYSIS METHOD: PCM

ANALYSIS METHOD:  
7400 circle one  
AHERA EPA LEVEL II

TECHNICIAN: ARTHUR TETTER

CONTACT: Benzie

| SAMPLE<br>NUMBER | SAMPLE<br>DESCRIPTION/LOCATION | SAMPLE<br>TYPE | PUMP<br># | FLOWRATE<br>START STOP | TIME<br>ON OFF | TOTAL<br>TIME | VOLUME<br>(Net #) | CONCENTR.<br>(lb./cc.) |
|------------------|--------------------------------|----------------|-----------|------------------------|----------------|---------------|-------------------|------------------------|
| 01               | EAST SIDE 44 GOLDST. ROOF      | 3              |           | 5 5                    | 0802 1230      | 270           | 1350              |                        |
| 02               | WEST SIDE 44 GOLDST. ROOF      | 3              |           | 5 5                    | 0802 1232      |               |                   |                        |
| 03               | WEST SIDE 44 GOLD ST. ROOF     | 3              |           | 5 5                    | 0803 1233      |               |                   |                        |
| 04               | EAST SIDE 44 GOLDST. ROOF      | 3              |           | 5 5                    | 0805 1235      |               |                   |                        |
| 05               | INSIDE 44 GOLDST. ROOF         | 3              |           | 5 5                    | 0809 1239      | 270           | 1350              |                        |
| 06               | Field Blanks                   | 1              |           |                        |                |               |                   |                        |
| 07               | Field Blanks                   | 1              |           |                        |                |               |                   |                        |
| 08               | Field Blanks                   | 1              |           |                        |                |               |                   |                        |

**COMMENTS:**

|              |                      |       |         |
|--------------|----------------------|-------|---------|
| SAMPLE BY:   | ARTHUR JETTER        | DATE: | 9/27/02 |
| SIGNATURE:   | <i>Arthur Jetter</i> |       |         |
| RELEASED BY: | ARTHUR JETTER        | DATE: | 9/27/02 |
| SIGNATURE:   | <i>Arthur Jetter</i> |       |         |
| RECEIVED BY: | ACATIGAY             | DATE: | 9/28/02 |
| SIGNATURE:   | <i>R. C. Giger</i>   |       |         |

T02-09-105

| SAMPLE TYPE CODES            |                               |
|------------------------------|-------------------------------|
| 1 - Blank                    | 5 - Final Clearance (inside)  |
| 2 - Pre-Abatement            | 6 - Final Clearance (outside) |
| 3 - During Abatement         | 7 - Personal                  |
| 4 - During Glove Bag Removal | 8 - Background                |

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

### Asbestos Inspection Report

|                                                                |                     |                                    |                    |                                          |                                     |                               |
|----------------------------------------------------------------|---------------------|------------------------------------|--------------------|------------------------------------------|-------------------------------------|-------------------------------|
| Premise No. <u>44 GOLD STREET</u>                              |                     |                                    |                    |                                          | Inspection Date:<br><u>09-27-02</u> |                               |
| Floor<br><u>ROOF</u>                                           | Zip<br><u>10038</u> | Borough<br><u>1</u>                | Block<br><u>76</u> | Lot<br><u>25</u>                         | Squad #<br><u>N/A</u>               | Badge #<br><u>A020</u>        |
| Inspector<br><u>Dennis Antzoulatos</u>                         |                     | Building Type<br><u>COMMERCIAL</u> |                    | Basis of Inspection<br><u>WTC Survey</u> |                                     | Photos Taken<br><u>Yes/No</u> |
| Contractor's Name<br><u>Benjamin Kurzban &amp; Son Control</u> |                     |                                    |                    | Sample Number<br><u>N/A</u>              |                                     |                               |
| Address City<br><u>1248 Ralph Avenue, Brooklyn</u>             |                     |                                    |                    | Sample Number<br><u>N/A</u>              |                                     |                               |
| State Zip Phone<br><u>NY 11236 (718)531-2900</u>               |                     |                                    |                    | Sample Number<br><u>N/A</u>              |                                     |                               |
| Laboratory Name<br><u>Warren &amp; Panzer Engineers Inc.</u>   |                     |                                    |                    | Owner's Name                             |                                     |                               |
| Address City<br><u>228 East 45 Street New York</u>             |                     |                                    |                    | Address City                             |                                     |                               |
| State Zip Phone<br><u>NY 10017 (212) 922-0077</u>              |                     |                                    |                    | State Zip Phone                          |                                     |                               |
| Contact Person                                                 |                     |                                    |                    | Time of Inspection from:<br><u>N/A</u>   |                                     |                               |

FRIDAY SEPTEMBER 27 2002

THE CLEAN UP OF THE ROOF OF THE PREMISE WAS  
CONDUCTED TODAY. AIR SAMPLING FOR THE CLEAN UP PROJECT WAS  
PERFORMED BY ARTHUR C. JETTER (CERTIFICATE # AH 97-06135  
EXP 03103) OF WARREN & PANZER. AFTER THE CLEAN UP ACTIVITIES  
WERE COMPLETED, I CONDUCTED A VISUAL INSPECTION OF THE  
CLEANED ROOF SURFACES AND OBSERVED NO VISIBLE WTC DEBRIS.  
THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.