

WTC Visual Survey Form

1001182

Premise Address: 44 GOLD ST		
Block: 76 Lot: 25	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building: The Country Cafe
# of Stories:	AKA's:	
Building Owner/Management: Name: Mustafa Sav.		Telephone Number: (212) 349-4290
Address: 44 GOLD ST		FAX: () (212) 797-6913
On Site Contact: Name: A Kitchen Supervisor		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:				
North	☐ N/A	Inspected	Debris	
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:				
Roof				
Debris: ☒ No Visible/Fine Layer ☒ ½ to 1" ☐ > 1"				
Description:				
Setbacks N/A ☒				
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments				

Date: 2/15/2002

Inspection Team: Name: RAMMOHAN

Agency: DEP.