


E172657C



NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION
Asbestos Control Program
 59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107
ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)

File 15494402
 Building Dept. or TRU No
 FOR OFFICIAL USE ONLY
 1. *Dep*
 (See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 55 FULTON STREET Borough MAN Zip 10038
 AKA 80 GOLD STREET 3. Block 94 4. Lot 1
 5. Type of Facility FOOTLOCKER 6. Name of Building _____

II. BUILDING OWNER

7. Name SOUTHBRIDGE TOWERS 8. Contact Person TONY MEDINA
 9. Tel. # _____ Fax # _____
 10. Address 80 GOLD STREET City NEW YORK State NY Zip 10038

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KUEZBAN & SON CONTROL INC 13. Contact Person LOUIE IANNICO
 14. Federal Employer ID. # _____ PII _____ 15. Tel. # (718) 531-2900 Fax # _____
 16. Address 124B RALPH AVENUE City BROOKLYN State NY Zip _____

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN
 19. Federal Employer ID. # _____ PII _____ 20. Tel. # (212) 922-0077 Fax # (212) 922-0680
 21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
 22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 09/21/02 Projected completion date 10/21/02
 Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday
 Shift from: 8⁰⁰ ☒ am ☐ pm to 8⁰⁰ ☐ am ☒ pm
 If other, specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work
8505 Square Feet, and/or 0 Linear Feet



DEP
 BUREAU OF ENVIRONMENTAL
 REMEDIATION & ENFORCEMENT
 ASBESTOS CONTROL
 PROGRAM
 TRU 12

ACP 7
 2/2001


ATHENICA

ENVIRONMENTAL SERVICES INC.

 Tel. (716) 784-7490
 Fax. (716) 784-4085

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

 CLIENT: Warren & Panzer Engineers, P.C.
 LABORATORY ID #: T02-09-079
 ANALYT. METHODOLOGY: AHERA
 FILTER TYPE: M.C.E.
 AVERAGE G.O. AREA (mm²): 0.013838

 PROJECT: NYC DEP, 55 Fulton St.
 DATE OF REPORT: 09/22/02
 DATE OF ANALYSIS: 09/22/02
 EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (L)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (struct./cm ³)	TOTAL ASBESTOS AIR CONC. (struct./cm ³)	TOTAL ASBESTOS FILTER CONC. (struct./mm ²)	AIR CONC. FOR 0.5-5.0µm	AIR CONC. FOR 0.5-5.0µm	ASBEST. TYPE CHYRS.	ANALYT. ASBEST. TYPE SPECIFY
01	T02-09-079-2465	Decon	1500	4	0.0554	0.0046	<0.0046	<18.07	NA	NA	NA	NA
02	T02-09-079-2466	West side of roof	1500	4	0.0554	0.0046	<0.0046	<18.07	NA	NA	NA	NA
03	T02-09-079-2467	Center of roof	1500	4	0.0554	0.0046	<0.0046	<18.07	NA	NA	NA	NA
04	T02-09-079-2468	South side of roof	1500	4	0.0554	0.0046	<0.0046	<18.07	NA	NA	NA	NA
05	T02-09-079-2469	Below roof	1500	4	0.0554	0.0046	<0.0046	<18.07	NA	NA	NA	NA

E. Sioukri

 ANALYST
 E. Sioukri

 LABORATORY DIRECTOR
 Spiro Dourgas

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, KLAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0830**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ⁺/a

W&P FILE #: 1079-01-02

CLIENT: NYC DEP

PROJECT: 1200F

LOCATION: 55 Fulton St

CONTACT:

LABORATORY: 95 HFA/C4

ANALYSIS METHOD:	PCM	TEMP	TEMP

circle one 7400 AHERA EPA LEVEL II

TECHNICIAN: FESTY O'SMULCON

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTRA (flb./cc.)
01	DECON	3		5 5	1100 1600	300	1500	
02	WEST SIDE OF ROOF	3		5 5	1102 1602	300	1500	
03	CENTER OF ROOF	3		5 5	1104 1604	300	1500	
04	SOUTH SIDE OF ROOF	3		5 5	1106 1606	300	1500	
05	BELOW ROOF	3		5 5	1108 1608	300	1500	
06	BLANK	1						
07	11	1						
08	11	1						

COMMENTS:

✓ 02-09-079

SAMPLE BY: FESTY CREMUE GTE DATE: 09-21-02

SIGNATURE:

RELEASED BY: FBI MEMPHIS DATE: 9-11-68

SIGNATURE:

RECEIVED BY: A. GILL DATE: 9/22/02

SIGNATURE:

SAMPLE TYPE CODES

1 - Blank

2 - Pre-Abatement

3 - During Abatement

4 - During Glove Bag Removal

5 - Final Clearance (inside)

6 - Final Clearance (outside)

7 - Personal

8 - Background



ATHENICA

ENVIRONMENTAL SERVICES INC.
TEL (718) 764-7400
FAX (718) 764-4085

CLIENT: Warren & Pauzer Engineers, P.C.
LABORATORY ID #: T02-09-084
ANALYT. METHODOLOGY: AHERA
FILTER TYPE: M.C.E.
AVERAGE G.O. AREA (mm²): 0.013838

AIRBORNE ASBESTOS ANALYSIS BY TRANSMISSION ELECTRON MICROSCOPY

PROJECT: NYC DEP, 55 Fulton St.
DATE OF REPORT: 09/24/02
DATE OF ANALYSIS: 09/24/02
EFFECTIVE FILTER AREA (mm²): 385

LABORATORY RESULTS

CLIENT #	LAB. ID #	LOCATION	VOLUME (ft ³)	G.O.'s ANALYZED	AREA ANALYZED (mm ²)	ANALYT. SENSITIVITY (air/cc/ft ³)	TOTAL ASBESTOS AIR CONC. (air/cc/ft ³)	TOTAL ASBESTOS FILTER CONC. (air/cc/ft ³)	AIR CONC. FOR STRUCT. 0.550 ft ³ /min	AIR CONC. FOR STRUCT. 0.550 ft ³ /min	ASBEST. TYPE CHRYS.	AMPHIB. ASBEST. TYPE SPECIFY
1	T02-09-084-2491	2 nd floor within 5ft of entrance to roof	1470	4	0.0554	0.0047	<0.0047	<18.07	NA	NA	NA	NA
2	T02-09-084-2492	On roof within 4ft of exit to roof	1470	4	0.0554	0.0047	<0.0047	<18.07	NA	NA	NA	NA
3	T02-09-084-2493	Center work area on roof	1470	4	0.0554	0.0047	<0.0047	<18.07	NA	NA	NA	NA
4	T02-09-084-2494	West section of WA on roof	1470	4	0.0554	0.0047	<0.0047	<18.07	NA	NA	NA	NA
5	T02-09-084-2495	Inside clean room of decon on roof	1470	4	0.0554	0.0047	<0.0047	<18.07	NA	NA	NA	NA

E. Siartin

ANALYST
E. Siartin

LABORATORY DIRECTOR
Spiro Donganis

LABORATORY CERTIFICATION NUMBERS: NVLAP 101958, ELAP 10955

- Athenica Environmental Services Inc. (AES), is responsible only for information pertaining to samples taken by its employees.
- Air sampling cassettes will be stored for sixty (60) days. AES Inc., should be notified within this time frame for a true duplicate analysis.
- If AES Inc., did not conduct the sampling, the reported airborne concentration was derived based on information provided by the client. Under these circumstances, the air concentration data is supplied solely for the convenience of the client.
- The report relates only to items tested. This report must not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. Test reports may not be reproduced except in full and with prior approval of AES Inc.
- The liability of Athenica Environmental Services Inc. with respect to the services charged, shall in no event exceed the amount of the invoice.

**228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

Fax (212) 922-0690

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate⁺/a

२०.

CLIENT: DEP.

W&P FILE #: 1079.01.02

CLIENT:

W&P FILE #: 10/9.81.02
LABORATORY: Warren and Lawzer.

CONTACT: *Mr. M. Nolan.*

PROJECT: DEP - Sanitary Clean-ups
LOCATION: 55 Fulton St., N.Y.C.

LABORATORY: WAKEN AND ECKERT

ANALYSIS METHOD: PCM TEM TEM TEM
circle one 7400 AHERA EPA LEVEL II

on the Roof.

TECHNICIAN: *Kir* *Bedin*

[illegible]

COMMENTS:

SAMPLE BY: Yusuf Bedn. DATE: 9-23-02.

SIGNATURE: U. Badi:

RELEASED BY: W. Yury Bedon. DATE: 9-23-02.

SIGNATURE: Cheryl Rubin Released - 19:00 PM.

RECEIVED BY: _____ DATE: 9/24/02

SIGNATURE: _____

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYST'S INFORMATION

Asbestos Inspection Report

Premise No. FOOT LOCKER RETAIL STORE 55 FULTON STREET AKA 80 GOLD STREET					Inspection Date: AS NOTED	
Floor ROOF	Zip 10038	Borough 1	Block 94	Lot 1	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes/ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name		
Address City 228 East 45 Street New York				Address City		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone		
Contact Person				Time of Inspection from: AS NOTED		
SATURDAY SEPTEMBER 21 2002 (800AM - 700AM)						
THE CLEAN UP OF THE ROOF OF THE PREMISE BEGAN TODAY. A REMOTE DECONTAMINATION UNIT WAS CONSTRUCTED ON THE ROOF OF THE PREMISE. ACCESS TO THE ROOF WAS THROUGH A HATCH ON THE SECOND FLOOR. A STEP OFF PAD WAS PLACED BELOW THE ROOF ACCESS HATCH. A "TEE PEE" WAS ERECTED ON THE ROOF AROUND THE ACCESS HATCH. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY FESTY OSEMWEGIE (CERTIFICATE # AH 01-01030) EXP 01/03). FOUR AIR SAMPLES WERE RUN ON THE ROOF AND ONE AIR SAMPLE WAS RUN ON THE SECOND FLOOR OF THE PREMISE BELOW THE ROOF ACCESS HATCH.						
SUNDAY SEPTEMBER 22 2002						
NO WORK WAS PERFORMED.						
MONDAY SEPTEMBER 23 2002 (800AM - 700PM)						
THE CLEAN UP OF THE ROOF OF THE PREMISE WAS COMPLETED TODAY. AIR SAMPLING FOR THIS PORTION OF THE CLEAN UP WAS PERFORMED BY YURI BEDIN (CERTIFICATE # AH 96-14947 EXP 02/03). THE SAMPLING LOCATIONS WERE IDENTICAL TO THE SAMPLING LOCATIONS OF SATURDAY SEPT. 21 2002. UPON COMPLETION OF THE CLEAN UP ACTIVITIES I CONDUCTED A VISUAL INSPECTION OF THE CLEANED WORK AREAS AND OBSERVED NO VISIBLE WTC DEBRIS. THE CLEAN UP PROJECT AT THE PREMISE IS NOW COMPLETE.						