

WTC Visual Survey Form

11-83352

Premise Address: 80 GOLD STREET Bldg # 1

Block: 94 **Residential** ☒ **Commercial** ☐ **Name of Building:**

Lot: 1 **Mix Use** ☐ **Other** ☐

of Stories: **AKA's:**

Building Owner/Management: South Ridge Mgmt **Telephone Number:** (212) 267-6190

Name: Tony Degido **FAX:** ()

Address:

On Site Contact:

Name: Angie, Super / Khan, Asst. Super. **Telephone Number:** ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☒ Yes ☐ No **Locations:** Various

ACM Clean Up ☐ Yes ☐ No **Locations:**

Air Monitoring ☒ Yes ☐ No **Locations:** Various

Copies of All Reports and Data Requested ☒ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description:

Setbacks N/A ☒

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 2/14/2002

Inspection Team: Name: Rammohan

Agency: NYC DEP

Name:

Agency:

WTC Visual Survey Form

1083352

Premise Address: 1012 Pearl St. (1012) 55 RULTON ST

Block: 94 **Residential** ☐ **Commercial** ☒ **Name of Building:** FOOT LOCKER

Lot: 1 **Mix Use** ☐ **Other** ☐

of Stories: **AKA's:**

Building Owner/Management: **Telephone Number:** ()

Name: **FAX:** ()

Address:

On Site Contact: **Telephone Number:** (212) 791-5530

Name: Carlos Carvajal

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☒ Yes ☐ No **Locations:**

ACM Clean Up ☐ Yes ☒ No **Locations:**

Air Monitoring ☐ Yes ☒ No **Locations:**

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Roof

Debris: ☐ ~~No Visible/Fine Layer~~ ☒ ½ to 1" ☐ > 1"

Description:

Setbacks N/A ☒

Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: <u> </u>	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 2/16 /2002Inspection Team: Name: R. Ramnathan Agency: DEPName: Agency: