

ATC Associates

104 East 25 Street, New York, NY 10010

Phone: (212) 353-8280 Fax: (212) 353-8306



Attn: Mr. Fabio Pedone
Warren & Panzer Engineers, P.C.
228 E. 45th Street
New York NY 10017

Received: 6/15/02 10:00:00 PM
ATC Group #: 8128
Analysis Date: 6/16/02

Fax: (212) 922-0630 Phone: (212) 922-0077
Project: NYC-DEP W & P File #: 1079.01.02
28 Trinity Place, NY

**Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed
by EPA 40 CFR Part 763 Final Rule (AHERA)**

Sample	Volume	Area Analyzed	Non Ash	Asbestos Type(s)	# Structures 0.5µ-5 µ	Analytical Sensitivity (S/cc)	Asbestos Concentration (S/mm ²)	(S/cc)	Notes
01 8/28 -1	1440.00	0.0562	0	CHRYSTOTILE	0	1	0.0048	17.79	0.0048
02 8/28 -2	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048
03 8/28 -3	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048
04 8/28 -4	1440.00	0.0562	0	None Detected	0	0	0.0048	<17.79	<0.0048
05 8/28 -5	1440.00	0.2248	0	CHRYSTOTILE	2	2	0.0048	71.17	0.0190

10x20

ROMAN PEYSAKHOV

Analyzed by:

MICHAEL A. GORYCKI, Ph.D.

Approved by:

Disclaimer: The laboratory is not responsible for data reported in structures/cc, which is dependent on volume collected by non-laboratory personnel. This lab is only responsible for data reported in structures/mm². This report may not be reproduced, except in full, without written approval by ATC Associates Inc. This report may not be used to claim product endorsement by NVLAP or any other agency of the U.S. Government. This report relates only to the samples reported above. Quality control data (including 95% confidence limits and laboratory and analysis accuracy and precision) is available upon request.

Accredited for NVLAP PLMTEM #101187-0, NY State ELAP #10879

228 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-0630

8128

WARREN & PANZER ENGINEERS, P.C.

AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

24 hr⁺/a

12 hr⁺/a

6 hr⁺/a

3 hr⁺/a

Immediate ⁺/a

P.O.

WRP FILE #: 1079 01.02

LABORATORY: ATC

CONTACT: NELSON

CLIENT: NYC DEP, NYS

PROJECT: ROOF CLEANING

LOCATION: 28 TRINITY PLACE NY

ANALYSIS METHOD: PCM
circle one

TEM
AHERA

TEM
EPA LEVEL II

TECHNICIAN: FAYED ELLIARDI

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START STOP	TIME ON OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb/cc)
01	STAIRWAY BET THE ROOFS	3		4 4	0955 1555	360	1440	
02	INSIDE THE DECK (CLEAR AREA)	3			0957 1557			
03	ACCESS TO THE ROOF	3			0958 1558			
04	ROOF RIGHT SIDE (WORK AREA)	3			0959 1559			
05	ROOF LEFT SIDE (WORK AREA)	3		4 4	1010 1600	360	1440	
06	FIELD BLDG	1						
07	"	1						
08	"	1						

COMMENTS:

SAMPLE BY: FAYED ELLIARDI	DATE: 06/15/02
SIGNATURE: F. Ellardi	
RELEASED BY: [Signature]	DATE: [Signature]
SIGNATURE: [Signature]	
RECEIVED BY: M. Boff	DATE: 06/15/02
SIGNATURE: [Signature]	22:00

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background