

FEB-25-2002 11:52

BANHM LABORATORY UNIT

P.01/01

BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

DUPLICATE

JOEL A. MIELS, SR., P.E.
 COMMISSIONER

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 2-23-02
 Premise: 28 TRINITY PL. Time: 3:00 AM/PM ☒
 Boro: MANHATTAN
 Inspector: SAM NEBEDUM Samuel Nebedum
 Print Sign

TURNAROUND TIME: 24HRS ☒ 48HRS ☐ 1 WK ☐ 2 WKS ☐ 4 WKS ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A038041	Fibrous	BACK FLOOR	099
2. 20223/A038042		SIDE WALL	100
3. 20223/A038043		SIDE WALL	101.
4.			
5.			
6.			
7.			
8.			
9.			
10.			

ANALYSES REQUESTED: Asbestos PLM ☒ Asbestos TEM ☐ Lead ☐

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	4:05P	PRINT <u>Greg Fruchtman</u> SIGN <u>Reg. Inf. Fr.</u>	Safe Custody BEC Lab
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

REV 12/97

TOTAL P.01

FEB-25-2002 11:51

BANHM LABORATORY UNIT

P.07/07

BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIREL, SR., P.E.
 COMMISSIONER

DUPLICATE

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____ Date Sampled: 2-23-02
 Premise: 67 GREENWICH STREET Time: 10:15 (am/pm)
 Boro: MANHATTAN
 Inspector: CARL Lutchmedial Carl Lutchmedial
 Print Sign

TURNAROUND TIME: 24HRS [✓] 48HRS [] 1 WK [] 2 WKS [] 4 WKS []

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223/A058012	Fibrous	ROOF (-)	996
2. 20223/A058013		(-)	997
3. 20223/A058014		(-)	998
4. 20223/A058015			999
5. 20223/A058016		(-)	001
6. 20223/A058017		(-)	002
7. 20223/A058018			003
8. 20223/A058019			004
9. 20223/A058020		(-)	005
10. 20223/A058021			006
10. 20223/A058022		(-)	007
20223/A058023		(-)	008

ANALYSES REQUESTED: Asbestos PCM [✓] Asbestos TEM [] Lead []
 20223/A058024 AM TR / CH-1.1%

DATE	TDE	ACCEPTED BY	COMMENTS
2/23/02	3:30p	PRINT Sam Nebedum SIGN Samuel Nebedum	transport to lab.
2/23/02	4:00p	Greg Fruchtman Raj, Jufan	Safe Cust of BEC Lab

BEP AND REV 8/96

TOTAL P.07



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 23, 2002

Irving Schachter
P.O. Box 112 Planetarium Station
New York, NY 10024-9998

**Subject: 67 GREENWICH STREET
28-30 Trinity Place
Second Notice**

Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.
Director
Asbestos Control Program




www.nyc.gov/dep

(718) DEP-HELP

28-30 TRINITY

19 11

BIN: 1000796



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Milele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

February 8, 2002

IRVING SCHACHTER
P.O BOX 112
NEW YORK, NY 10024

Subject: 67 GREENWICH STREET, MANHATTAN

Dear Sir/ Madam:

The New York City Department of Environmental Protection in cooperation with the New York State Department of Labor and the United States Environmental Protection Agency has continued inspections/surveys of buildings in the vicinity of the World Trade Center.

During the recent inspections/surveys, visible debris from the collapse of the Towers was observed on the roof, setbacks, and/or facades of the above referenced building. In accordance with previously issued guidelines, copies of which are enclosed, these accumulations must be assessed by a NYC DEP certified investigator to determine whether the material is asbestos-containing material and then cleaned up appropriately.

Building owners are responsible for the cleaning of building exteriors, grounds, and common area. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP.

Sincerely,

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP