

WTC Visual Survey Form

Premise Address: 42 TRINITY PLACE		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	Sims Store
# of Stories: 5	AKA's:	
Building Owner/Management:		Telephone Number: () not given
Name: Gould (Store mn)		FAX: ()
Address:		
On Site Contact:		
Name: Mr Gould		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: Submitted already		
ACM Clean Up ☐ Yes ☒ No Locations:		
Air Monitoring ☒ Yes ☒ No Locations:		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☒ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: Painted concrete etc					
Roof					
Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.					
Description:					
Setbacks N/A ☐					
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:		Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments					

Date: 1/25/2002

 Inspection Team: Name: Carla Hutchinson Agency: DCP
 Name: _____ Agency: _____

WTC Visual Survey Form

Premise Address: 42 TRINITY PLACE ?

Block: Residential ☐ Commercial ☒ **Name of Building:** Sims Store

Lot: **Mix Use** ☐ **Other** ☐

of Stories: 5 **AKA's:**

Building Owner/Management: Name: Gould (Store Mn) Telephone Number: () not given
FAX: ()

Address:

On Site Contact: Name: Mr Gould Telephone Number: ()

Building Owner Management Activities

Interior Survey Performed ☒ Yes ☐ No
Exterior Survey Performed ☒ Yes ☐ No
General Clean Up ☒ Yes ☐ No Locations: Submitted already
ACM Clean Up ☐ Yes ☒ No Locations:
Air Monitoring ☒ Yes ☒ No Locations:

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description:

Broken windows etc...

Roof

Debris: ☒ No Visible /Fine Layer ^{light dust} ☐ ½ to 1" of dust ☐ > 1" of dust.

Description:

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/25/2002

Inspection Team: Name:

CARE LUTCHMANN

Agency: DCP

Name:

Agency:



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Milele Sr., P.E.
Commissioner**

Robert C. Avaltroni
Deputy Commissioner
Bureau of
Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422

EL758388163US

February 12, 2002

Building Owner
42 Trinity Place
New York, NY 10006

Subject: 69 GREENWICH STREET
42 Trinity Place

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.

Director

Asbestos Control Program



www.nyc.gov/dep

(718) DEP-HELP