

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 02/22/2002 09:57 AM

Submitted By

Page 1

Service # 412990

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 44 TRINITY PL 1 Aka 81 Greenwich St.
10006
Cross Streets EXCHANGE ALLY
RECTOR ST

Compass Direction

Building ID 10007

Block 00019

Lot 0018

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 02/21/2002 16:25

Taken By 7223

SMITH, BRENDON

Responsibility BHZ

BANHAZMAT (AIR, NOISE, HAZ. MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

☐ Customer Contact Req

Budget #

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

COMPLETED

Problem Comments

Initial Caller

Last Name

First Name, MI

Address

PII

Title MR

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

Reference #

PII

Evening Phone (732)663-0904 x

Call Date 02/21/2002 16:25

Caller Comments

compl requests info. regarding air quality/asbestos info in 44 trinity & 46 trinity. compl can be reached at given phone #. pls contact compl for info.

Inspected

Resolution

By

RAM.

Date

2/28/02

Time

12³⁰

Code

Date

2/28

Time

1¹⁵Thurs. 11³⁰am to 1:30pm

Merlon Mgmt Corp

(212) 473-6359

49 1/2 First Ave
my my

Window exterior & ledges contains
fine dust. Apt #6 cleaned by landlord
Sent clean-up crew. No air testing done.
The Complainant sent dust sample to lab - ve

46 Trinity contains visible accumulations of
WTC debris on facade & awning.

871833
850816

① Song DCR TRV
25

TRV 27

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 02/28/2002 03:42 PM

Submitted By

Page 1

Service # 412990

Problem BWTC ASBESTOS: WTC (USE COMMENTS)

Address 44 TRINITY PL 1

10006

Cross Streets EXCHANGE ALLY
RECTOR ST

Compass Direction

Building ID 10007

Block 00019

Lot 0018

CMBD 101

Location

Area

Sub-Area 101

District

Parcel

of Calls 1

Duration of Call 00:00

Call Date 02/21/2002 16:25

Taken By 7223

SMITH, BRENDON

Responsibility BHZ

BANHAZMAT (AIR,NOISE,HAZ.MAT)

Priority

Scheduled Date

Inspector

Due Date

Asset

Avg Insp Duration

Avg Insp Days 0

Avg Insp Hrs 0

Avg Insp Mins 0

☐ Customer Contact Req

Budget #

Problem Comments

Initial Caller

Last Name

First Name, MI

Address

Title MR

City, State/Province, ZIP/PC

☐ Foreign

Day Phone

Evening Phone

Reference #

PII

Call Date 02/21/2002 16:25

Caller Comments

compl requests info. regarding air quality/asbestos info in 44 trinity & 46 trinity. compl can be reached at given phone #. pls contact compl for info.

Inspected

Resolution

By	Date	Time	Code	Date	Time
By Car Ram					

Thurs. 11:30 AM - 1:30 PM