

WTC Visual Survey Form

1000798

Premise Address: <u>81 Greenwich St.</u>		
Block: <u>19</u>	Residential ☐ Commercial ☐	Name of Building:
Lot: <u>18</u>	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>44 TRINITY PLACE</u>	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name: <u>XONE</u>		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North ☐ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
West ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
Facade Description: _____ _____			
Roof			
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"			
Description: <u>NO ACCESS</u> _____ _____			
Setbacks ☐ N/A			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments _____ _____ _____ _____			

Date: 3.5 /2002Inspection by: Name: CARL

Agency: _____

Name: _____

Agency: _____

WTC Visual Survey Form

Premise Address: 81 GREENWICH STREET		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's: 44 TRINITY PLACE	
Building Owner/Management:		Telephone Number: (212) 473-6359
Name: EBW LLC		FAX: ()
Address: 49 FIRST AVENUE		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected		Debris	
North	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description: AWNING AT 81 GREENWICH IS DIRTY AWNING AT 81 GREENWICH IS DIRTY					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ^{Light dust} ☐ > 1" ^{1 dust}					
Description: NO ACCESS TO THE ROOF - HAD CONTACT INFO LEFT MESSAGE ST EXT. 212 AT OWNER ABOVE					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					
RE-INSPECTION AT OWNER'S REQUEST - VISIBLE DEBRIS NOTED ABOVE @ FACADE DESCRIPTION					

Date: 3/27/2002
ENTERED

Inspection Team: Name: C. LUTCHMEDIAL Agency: NYCDEP
Name: _____ Agency: _____

WTC Visual Survey Form

Premise Address: 81 Greenwich St		
Block:	Residential ☐ Commercial ☒	Name of Building: Blumpe
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name: None		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description:					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 5/16/2002

Inspection Team: Name: CAZEL

Agency: _____

Name: _____

Agency: _____

ENTERED