

Post-It® Fax Note		7671	Date	3/29/02	# of pages	1
To	BERNARD McElhone		From	Penny Theodorely		
Co./Dept.	MERLON		Co.	NYC DEP		
Phone #	(212) 473-6359		Phone #	(212) 595-3657		
Fax #	(212) 979-9027		Fax #	(212) 595-3744		



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

March 5, 2002

EBW LLC
49 ½ First Avenue
New York, New York 10003-9402

Subject: 44 Trinity Place, New York

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☐ setback(s)
- ☐ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by March 19, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E

Director

Asbestos Control Program



(718) DEP-HELP



The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
Corona, New York
11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422

Post-It Fax Note	7671	Date	3/27/02	# of pages	1
To	BERNARD McElhorne	From	Penny Thodorellis		
Company	WYERLON	Co.	NYC DEP		
Phone	(212) 473-6359	Phone	(212) 595-3657		
Fax	(212) 979-9027	Fax	(212) 595-3744		



March 5, 2002

EBW LLC
49 1/2 First Avenue
New York, New York 10003-9402

Subject: 44 Trinity Place, New York

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☐ setback(s)
- ☐ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by March 19, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

Penny Thodorellis
R. Radhakrishnan, P.E.
Director
Asbestos Control Program

718 595 3648-*****

-NYCDEP BRN/HM ASB/LEAD TRU-

912129799027 000/001 00:00'00"

STATION NAME/TEL.NO. PAGES DURATION

FILE NO. = 217

MODE = MEMORY TRANSMISSION START=MAR-27 09:58 END=MAR-27 10:20

*****-COMM. JOURNAL-***** DATE MAR-27-2002 ***** TIME 10:20 *** P.01



The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Corona, New York
 11368-3107

Joel A. Mile Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of Environmental Compliance
 Tel (718) 595-4418
 Fax (718) 595-4422

March 5, 2002

EBW LLC
 49 1/2 First Avenue
 New York, New York 10003-9402

Subject: 44 Trinity Place, New York

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☐ setback(s)
- ☐ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by March 19, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E
Director
Asbestos Control Program

Date	3/27/02	# of pages	1
To	Penny Theodorelly		
From	NYC DEP		
Phone	(718) 595-3657		
Fax	(718) 595-3744		
Post-it Fax Note	7671		
To	BERNARD McEIlhone		
From	CRITERION		
Phone	(718) 473-6359		
Fax	(718) 979-9027		



718 595 3648-*****

-NYCDEP BAHM ASB/LEAD TRU-

000/001 00:00'00"

912129799027

634 8 001

PAGES DURATION

STATION NAME/TEL.NO.

ADDR NO.

COM STN NO.

FILE NO. = 211

END=MAR-27 09:32

START=MAR-27 09:11

MODE = MEMORY TRANSMISSION

*****-COMM. JOURNAL-***** DATE MAR-27-2002 TIME 09:32 *** P.01