

WTC Visual Survey Form

Premise Address: <u>83 Greenwich St</u>		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories: <u>7</u>	AKA's:	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		Telephone Number: ()
Name:		
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: _____					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 6/19/2002Inspection Team: Name: Dennis White

Agency: _____

Name: _____

Agency: _____

ENTERED

WTC Visual Survey Form 83 Greenwich

Premise Address: 46 TRINITY PLACE			
Block: 9	☐ Residential	☒ Commercial	Name of Building:
Lot: 9	☐ Mix Use	☐ Other	
# of Stories: 5	AKA's: 83 GREENWICH STREET		
Building Owner/Management:		Telephone Number: (212) 486 1122	
Name: FRED MAROLDA		FAX: ()	
Address:			
On Site Contact:		Telephone Number: ()	
Name: FRED			
Building Owner Management Activities			
Interior Survey Performed ☒ Yes ☐ No		Submitted & ready	
Exterior Survey Performed ☒ Yes ☐ No			
General Clean Up ☒ Yes ☐ No			
ACM Clean Up ☐ Yes ☐ No			
Air Monitoring ☒ Yes ☐ No			
Locations:		Locations:	
Locations:		Locations:	
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:			
North ☒ N/A South ☒ N/A East ☐ N/A West ☐ N/A	Inspected		Debris
	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
	☒ Yes ☐ No	☒ Yes ☐ No	☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
Facade Description: <u>Broken windows etc...</u> To clean facade weather permitting			
Roof			
Debris: ☐ No Visible /Fine Layer <u>light dust</u> ☒ 1/2 to 1" of dust ☒ > 1" of dust.			
Description: <u>Lodges has ~ 1/2 in debris -</u>			
<u>Roof is clean in some areas</u>			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Comments <u>Said will clean roof + facade soon</u>			
<u>To test roof</u>			

Date: 1/25/2002

Inspection Team: Name: CARL HUTCHINGS Agency: DEP

Name: _____ Agency: _____