

WTC Visual Survey Form

Premise Address: <u>16 Rector St</u>		
Block:	Residential ☐ Commercial ☐	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's: <u>94 Greenwich St</u>	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected		Debris	
North	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
East	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West	☐ N/A	☐ Yes	☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
Facade Description:					
Roof					
Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☒ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor:	<u>1</u>	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor:	_____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments					

Date: 1/26/2002Inspection by: Name: Cape
Name: _____Agency: DCR
Agency: _____

WTC Visual Survey Form

Premise Address: <u>116 Rector St - Closed</u>		
Block: <u>53</u>	Residential ☐ Commercial ☒	Name of Building: <u>Liberty Smoke Shop</u>
Lot: <u>41</u>	Mix Use ☐ Other ☐	
# of Stories: <u>4</u>	AKA's: <u>94 Greenwich</u>	
Building Owner/Management:		Telephone Number: ()
Name:		FAX: ()
Address:		
On Site Contact:		
Name:		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:			
North ☐ N/A	Inspected ☐ Yes ☐ No	Debris ☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
East ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
West ☐ N/A	☒ Yes ☐ No	☐ No Visible/Fine Layer	☒ ½ to 1" ☐ > 1"
Facade Description: _____			
Roof			
Debris: ☒ No Visible/Fine Layer ☐ ½ to 1" ☒ > 1" ✓ correct response			
Description: <u>inspected roof of 105 Washington St</u>			
Setbacks N/A ☐			
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Comments			

Date: 1/26/2002 Inspection Team: Name: CARL Agency: DGP
 Name: _____ Agency: _____

Page: 1 Document Name: Extra

ADDRESS EXISTS WITH A.K.A.S WHICH HAVE THE SAME BIN

01/30/02 PUBLIC ACCESS PROPERTY PROFILE OVERVIEW BISPIQ70
16..... RECTOR STREET..... 1 MANHATTAN 10006 BIN# 1001058

RECTOR STREET 14 - 18 HEALTH AREA : 77 TAX BLK: 53...
GREENWICH STREET 94 - 94 CENSUS TRACT: 13 TAX LOT: 41...
COMMUNITY BD: 101 CONDO :
MULTI STRUCT: 01 VACANT :

=====

DOB SPECIAL PLACE NAME :	1	PROPERTY RECORD(S)
DOB BUILDING REMARKS :		
FINANCE OCCUPANCY CODE : S9-RESIDENCE-MULTI-U		LANDMARK STATUS:

COUNTS FOR THIS BIN		RECORD VERIFIED :
ACTIONS : 41 , 6	JOBS/FILINGS (PF4)	SPECIAL STATUS :
VIOLATIONS DOB : 8 , 2	OPEN	LOCAL LAW :
ECB : 8 , 4	OPEN (PF12)	SRO :
COMPLAINTS : 12 , 0	OPEN (PF11)	

PF 3 = ELEVATORS	ENTER KEY= ACTIONS	PF 5/6/7 = NEW ADDR/BIN/BLK-LOT
PF 8 = BOILERS	(TYPE :)	PF 9/10 = BROWSE BIN/BLK-LOT
*NO ARA'S FILED		PF 15 = BROWSE 1 PROPERTY RECORDS
PF 14 = LPC/HPD/LOFT USE ONLY		PF 16 = ADDTN'L PROPERTY INFO

Date: 1/30/ 2 Time: 01:38:48 PM