


96 GREENWICH STREET



WTC Visual Survey Form

40 71 93
 Premise Address: 96 Greenwich St. / 94 1/2 Greenwich / 94 Greenwich
 Block: 96 Residential ☐ Commercial ☐ Name of Building:
 Lot: 94 1/2 Mix Use ☐ Other ☐
 # of Stories: 94 AKA's:
 Building Owner/Management: Telephone Number: ()
 Name: FAX: ()
 Address:
 On Site Contact: Telephone Number: ()
 Name:
 Building Owner Management Activities
 Interior Survey Performed ☐ Yes ☐ No
 Exterior Survey Performed ☐ Yes ☐ No
 General Clean Up ☐ Yes ☐ No Locations: _____
 ACM Clean Up ☐ Yes ☐ No Locations: _____
 Air Monitoring ☐ Yes ☐ No Locations: _____
 Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

North ☐ N/A	Inspected ☒ Yes ☐ No	Debris ☐ No Visible/Fine Layer ☒ 1/2 to 1" ☐ > 1"
South ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
East ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
West ☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☒ 1/2 to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"

Comments

Date: 1 / 26 / 2002 Inspection by: Name: C.L Agency: _____
 Name: _____ Agency: _____