

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME <u>Care Hutchins</u> LOCATION <u>94 1/2 Greenwich St</u>	BADGE # <u>A058</u>	DATE <u>2/23/02</u>
---	-----------------------------------	-----------------------------------

ROOF

☐ No Visible Debris

☒ Entire Roof Covered with Debris

☐ Partial Roof Covered

☐ Local/Isolated Areas
☐ Gutters
☐ 25% of the roof
☐ 50% of the roof
☐ 75% of the roof

FACADE

☐ Clean

☐ Entire Facade req. Clean-up

☐ _____ Req. Clean-up

West

South

North


Greenwich St

Rear Portion of Roof Only

Samples A038 - - -

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME CARL LUTCHMANN BADGE # A058 DATE 2/23/02
 LOCATION 94 1/2 Greenwich St



**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>CARL LUTCHMAN</u> LOCATION <u>94 1/2 Greenwich St</u>	BADGE # <u>A038</u>	DATE <u>2/23/02</u>
---	-----------------------------------	-----------------------------------

X

West

South

X 021

X 022

X 023

X 025

X 024

X 026

X 027

X 028

X 029

X 030

N/A

Roof
Portion
of
Roof
Only

Greenwich St

Samples A038 - - -

ASBESTOS CONTROL PROGRAM EMERGENCY RESPONSE DIAGRAM

NAME <u>Carl Lutchmeyer</u>	BADGE # <u>A058</u>	DATE <u>2/23/02</u>
LOCATION _____		

ROOF

☐ No Visible Debris

☒ Entire Roof Covered with Debris

☐ Partial Roof Covered

☐ Local/Isolated Areas
☐ Gutters
☐ 25% of the roof
☐ 50% of the roof
☐ 75% of the roof

FACADE

☒ Clean

☐ Entire Facade req. Clean-up

☐ _____ Req. Clean-up

West

South

North

Rear Roof Only

Greenwich St

Samples A038 - - -

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>CARL LUTCHMOUTH</u>	BADGE # <u>A038</u>	DATE <u>2/23/03</u>
LOCATION _____		

X

X

West

South

North

Rear Roof

Only

Greenwich St

Samples A038 - - -

⊗ 011	⊗ 013	⊗ 014
⊗ 012	⊗ 016	⊗ 015
⊗ 020	⊗ 019	⊗ 018

**ASBESTOS CONTROL PROGRAM
EMERGENCY RESPONSE
DIAGRAM**

NAME <u>CARL LUTCHINSKI</u>	BADGE # <u>A038</u>	DATE <u>2/23/02</u>
LOCATION _____		

X

X

West

South

North

Rear Roof

Only

Greenwich St

Samples A038 - - -

BUREAU OF AIR, NOISE & HAZARDOUS MATERIALS
ASBESTOS/LEAD CONTROL PROGRAM
59-17 JUNCTION BOULEVARD
CORONA, NY 11368

JOEL A. MIELE, SR., P.E.
 COMMISSIONER

DUPLICATE

ASBESTOS CONTROL PROGRAM
BULK ANALYSIS CHAIN OF CUSTODY

Incident No.: _____

Date Sampled: 2-23-02

Premise: 94 1/2 GREENWICH STREET

Time: 2:15 am/pm (pm)

Boro: MANHATTAN

Inspector: SAM NEBEDUM
 Print

Samuel Nebedum
 Sign

TURNAROUND TIME: 24HRS ☒ 48HRS ☐ 1 WK ☐ 2 WKS ☐ 4 WKS ☐

SAMPLE NUMBER	DESCRIPTION	LOCATION SAMPLED	LAB ID
1. 20223 A038021	Fibrous	Roof	079
2. 20223 A038022			080
3. 20223 A038023			081
4. 20223 A038024		(-)	082
5. 20223 A038025			083
6. 20223 A038026		(-)	084
7. 20223 A038027			085
8. 20223 A038028			086
9. 20223 A038029		(-)	087
10. 20223 A038030			088

ANALYSES REQUESTED: Asbestos PLM ☒ Asbestos TEM ☐ Lead ☐

DATE	TIME	ACCEPTED BY	COMMENTS
2/23/02	4:05 P	PRINT Greg Frychtman SIGN <u>[Signature]</u>	Safe Custody BEC 686
		P	
		S	
		P	
		S	
		P	
		S	
		P	
		S	

DEP ACP REV 9/96

94 1/2 GREENWICH STREET

