

# WTC Visual Survey Form

**Premise Address:** 108 Greenwich St ?

**Block:** **Residential** ☐ **Commercial** ☒ **Name of Building:**

**Lot:** **Mix Use** ☐ **Other** ☐

**# of Stories:** 7 **AKA's:**

**Building Owner/Management:** Name: None **Telephone Number:** ( ) **FAX:** ( )

**Address:**

**On Site Contact:** **Name:** **Telephone Number:** ( )

**Building Owner Management Activities**

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No **Locations:** \_\_\_\_\_

ACM Clean Up ☐ Yes ☐ No **Locations:** \_\_\_\_\_

Air Monitoring ☐ Yes ☐ No **Locations:** \_\_\_\_\_

**Copies of All Reports and Data Requested** ☐ Yes

## Visual Inspection Results:

### Facade:

|       |                                         | <b>Inspected</b>                                                    | <b>Debris</b>                                             |                                  |                               |
|-------|-----------------------------------------|---------------------------------------------------------------------|-----------------------------------------------------------|----------------------------------|-------------------------------|
| North | <input checked="" type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No            | <input type="checkbox"/> No Visible/Fine Layer            | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| South | <input checked="" type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No            | <input type="checkbox"/> No Visible/Fine Layer            | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| East  | <input checked="" type="checkbox"/> N/A | <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No | <input checked="" type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| West  | <input checked="" type="checkbox"/> N/A | <input type="checkbox"/> Yes <input type="checkbox"/> No            | <input type="checkbox"/> No Visible/Fine Layer            | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |

**Facade Description:** \_\_\_\_\_

### Roof

**Debris:** ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

**Description:** \_\_\_\_\_

### Setbacks N/A ☐

|              |                                                        |                                  |                               |
|--------------|--------------------------------------------------------|----------------------------------|-------------------------------|
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |
| Floor: _____ | Debris: <input type="checkbox"/> No Visible/Fine Layer | <input type="checkbox"/> ½ to 1" | <input type="checkbox"/> > 1" |

### Comments

No Building Rep Available

**Date:** 1/25/2002

**Inspection Team: Name:** CARL

**Agency:** DEP



**Department of  
Environmental  
Protection**

59-17 Junction Boulevard  
Corona, New York  
11368-5107

**Joel A. Miele Sr., P.E.  
Commissioner**

**Robert C. Avaltroni  
Deputy Commissioner**

**Bureau of  
Environmental Compliance**  
Tel (718) 595-4418  
Fax (718) 595-4422

February 23, 2002

Joseph M. Martuscello  
108 Greenwich Street  
New York, NY 10006-1821

**Subject: 108 GREENWICH STREET  
Second Notice**

Dear Sir/ Madam:

This is a follow-up to the NYC DEP request for copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. To date, our office has not received the requested documents and information. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8<sup>th</sup> floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.  
Director  
Asbestos Control Program



(718) DEP-HELP