

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Inspection Detail

Report Date 04/05/2002 05:27 PM Submitted By Page 1

Service # 422357
Problem BWTCH WTC RELATED (HOT LINE)
Address 106 GREENWICH ST 1
10006
Cross Streets RECTOR ST
CARLISLE ST
Compass Direction
Building ID 10010 **Block** 00053 **Lot** 0036 **CMBD** 101

Location Area **District**
Sub-Area 101 **Parcel**

of Calls 1 **Duration of Call** 00:00 **Call Date** 03/19/2002 17:52
Taken By 2862 **FREYRE, RICARDO**
Responsibility BHZ **BANHAZMAT (AIR,NOISE,HAZ.MAT)**
Scheduled Date 03/19/2002 17:52 **Priority**
Inspector 5397 **PLUMPTRE, ALPHONSO** **Start Date** 03/19/2002 17:52
Due Date **Inspection Date** 03/22/2002 13:30
Resolution Code B2 **ASBESTOS,NO VIOLATION** ☐ **No Work Orders Required**
Asset **Resolution Date** 03/22/2002 13:40
Avg Insp Duration ☐ **Customer Contact Req**
Avg Insp Days 0 **Budget #**
Avg Insp Hrs 0
Avg Insp Mins 0

Problem Comments DEP HAS NOT RECEIVED ANY INFORMATION FROM THE OWNER.

THIS COMPLAINT WAS FORWARDED TO THE ASBESTOS UNIT FOR APPROPRIATE ACTION.

LEFT MESSAGE ON 3/20/02 AT 9:00 AM

I INSPECTED APARTMENTS 5,9,10,4 AND 1. IN # 5 THE EXTERIOR WASHING OF THE WINDOWS ALLOWED SOME MATERLAS TO COME INTO THE APARTMENT LIKEWISE IN APARTMENTS 9 AND 10. IN APARTMENT 4 THERE ARE STILL DUSTS ON THE FLOOR AND THE WINDOWSILLS. LATER ON I CONTACTED THE MANAGING AGENT MS. WILLIAMS WHO PROMISED TO SEND CREW TO RECLEAN THE APARTMENTS AND ENTIRE HALLWAYS INCLUDING AIR MONITORING AFTER CLEANUP.

Initial Caller

Last Name **Title**
First Name, MI PII
Address 106 GREENWICH STREET
City, State/Province, ZIP/PC
☐ **Foreign**
Day Phone (212)406-1295 x **Evening Phone** PII **Call Date** 03/19/2002 17:52
Reference #

Caller Comments CALLER INDICATES THAT HER BUILDING IS FULL OF DUST. MANAGEMENT SAYS THAT THE BUILDING WAS TESTED BUT IS REFUSING TO GIVE HER THE RESULTS. DEP HAS NO RECORD THAT HER BUILDING HAS BEEN CLEANED OR TESTED. THE BUILDING IS PRESENTLY VACANT DUE TO THE DUST IN THE BUILDING. ONE APARTMENT THAT WAS SUPPOSEDLY TESTED CAME BACK POSITIVE FOR ASBESTOS. REQUESTS THAT BUILDING BE CHECKED
THIS WAS CALLED IN BY: PII

Work Orders	Activity	Asset	Act Type	Act Group	Initiated	Scheduled	Completed	Source	Maint Type
Work Order #	Problem	Project	Pr Type	Unit ID		To Type	Unit ID		#

There are no work orders for this service number

Assets	From Type	Unit ID	To Type	Unit ID	#	Qualifier
--------	-----------	---------	---------	---------	---	-----------

There are no assets

Linked Requests

Service #	Problem	Problem Date	Address
-----------	---------	--------------	---------

No Linked Requests for this Service Request Inspection

NYC DEP

Method
Source
Critical Service







