

WTC Visual Survey Form

125 Greenwich

Premise Address: 113-123 Greenwich St.		
Block:	Residential ☐ Commercial ☒	Name of Building: AMEY
Lot:	Mix Use ☐ Other ☐	
# of Stories: 10	AKA's: 78 Trinity Place	
Building Owner/Management:		Telephone Number: (212) 306-1180
Name: CAROL Hoover - VP		FAX: ()
Address:		
On Site Contact:		
Name: Same		Telephone Number: ()
Building Owner Management Activities		
Interior Survey Performed ☒ Yes ☐ No		
Exterior Survey Performed ☒ Yes ☐ No		
General Clean Up ☒ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☒ No Locations: _____		
Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: _____

Roof

Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 1/26/2002

Inspection Team: Name: CAROL LUTCHMAN-FOUR Agency: D-7

Name: _____ Agency: _____

WTC Visual Survey Form

Premise Address: 125 GREENWICH ST			
Block:	Residential ☐	Commercial ☒	Name of Building: AMEX
Lot:	Mix Use ☐	Other ☐	
# of Stories:	AKA's:		
Building Owner/Management:		Telephone Number: ()	
Name:		FAX: ()	
Address:			
On Site Contact:			
Name: CAROL Hoover UP		Telephone Number: ()	
Building Owner Management Activities			
Interior Survey Performed ☐ Yes ☐ No			
Exterior Survey Performed ☐ Yes ☐ No			
General Clean Up ☐ Yes ☐ No		Locations: _____	
ACM Clean Up ☐ Yes ☐ No		Locations: _____	
Air Monitoring ☐ Yes ☐ No		Locations: _____	
Copies of All Reports and Data Requested ☐ Yes			

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	☐ Yes ☐ No	Debris	☐ No Visible/Fine Layer
South	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
West	☐ N/A	☒ Yes ☐ No	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ 1/2 to 1" ☐ > 1"
Facade Description: _____					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1"					
Description: _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments					

Date: 5/20/2002

Inspection Team: Name: CARL

Agency: _____

Name: _____

Agency: _____

ENTERED

WTC Visual Survey Form

125 GREENWICH
1001034

Premise Address: <u>88 TRINITY PLACE</u>		
Block: <u>51</u>	Residential ☐ Commercial ☒	Name of Building: <u>American Stock Exchange</u>
Lot: <u>14</u>	Mix Use ☐ Other ☐	
# of Stories: <u>15</u>	AKA's: <u>22 THAMES / 125-129 GREENWICH ST</u>	
Building Owner/Management: Name: <u>Carol Hoover VP (AMEX)</u>		Telephone Number: <u>(212) 306 1180</u>
Address: <u>88 Trinity Pl</u>		FAX: <u>()</u>
On Site Contact: Name: <u>Thomas S. Sacharewitz</u>		Telephone Number: <u>(212) 306 1663</u>
Building Owner Management Activities Interior Survey Performed ☒ Yes ☐ No Exterior Survey Performed ☒ Yes ☐ No General Clean Up ☒ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☒ No Locations: _____ Air Monitoring ☒ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☒ Yes		

Visual Inspection Results:

Facade:

	Inspected	Debris
North ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
South ☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
East ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
West ☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Facade Description:

Broken windows etc...

Roof

 Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" of dust ☒ > 1" of dust.

Description:

To test and cleanSetbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ ½ to 1" ☐ > 1"

Comments

RALPH RACANIELLO, V.P.AMERICAN STOCK EXCHANGE/NASDAQ88 TRINITY PLACENEW YORK, N.Y.Date: 1/25/2002Inspection Team: Name: Carol LutzmeierAgency: DEP

Name: _____

Agency: _____