

**BENJAMIN KURZBAN
& SON CONTROL, INC.**1248 Ralph Ave.
BROOKLYN, N.Y. 11236

(718) 531-2900

INVOICE

1154

TO
 Dept of Environmental Protection
 59-17 Junction Blvd
 Corona, New York 11378

DATE 8/1/02	ORDER NO.
SHIP TO Re: Contract REM-ROF2	

SALESPERSON	DATE SHIPPED	SHIPPED VIA	F.O.B. POINT	TERMS
QUANTITY	DESCRIPTION			UNIT PRICE - TOTAL
>	For work completed at 102-104 Fulton St			
	Registration# CT82620020015280			
	Pin# 82602WTCROOF2			
	5090 SF @ 2/Sf			
	Total Amount Due this Invoice			\$10,180.00

ORIGINAL

-34

Thank You!

-77

22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 08/22/02 Projected completion date 09/22/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday


Shift from: 8⁰⁰ ☒ am ☐ pm to 8⁰⁰ ☐ am ☒ pm

If other, specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

5090 Square Feet, and/or 0 Linear Feet



DEPT OF ENVIRONMENTAL
 CONSERVATION
 ASBESTOS CONTROL
 PROGRAM
 TRU 2

E106WTC

ONLY
TYPEWRITERS
OR
COMPUTERS
MAY BE USED
FOR
OFFICIAL USE ONLY




NYC DEPARTMENT OF ENVIRONMENTAL PROTECTION

Asbestos Control Program

59-17 Junction Boulevard, 8th Floor, Corona, NY 11368-5107

ASBESTOS PROJECT NOTIFICATION
(ASBESTOS INSPECTION REPORT)



Building Dept. or TRU No
FOR OFFICIAL USE ONLY

1. NYC DEP
(See fee schedule)

When submitting this form at the NYC Department of Buildings, the original form and three (3) copies with original signatures are required. Submittal at the NYCDEP requires one copy of the form with original signatures. This form must be submitted to the NYC DEP not less than one week in advance of the start of abatement activities.

I. FACILITY

2. Address 102-104 FULTON STREET Borough MN Zip 10038
AKA _____ 3. Block 78 4. Lot 21
5. Type of Facility COMMERCIAL 6. Name of Building _____

II. BUILDING OWNER

7. Name LEGACY FULTON STREET CORP. 8. Contact Person YAIR LIVY
9. Tel. # (516) 466-4992 Fax # (516) 466-4952
10. Address 111 GREAT NECK ROAD SUITE 205 City GREAT NECK State NY Zip 11021

III. GENERAL CONTRACTOR

11. Name _____ Tel. # _____

IV. ASBESTOS ABATEMENT CONTRACTOR

12. Name BENJAMIN KURZBAN & SON CONTROL 13. Contact Person LOUIE IANNICO
14. Federal Employer ID. # PII 15. Tel. # (718) 531-2900 Fax # (718) 209-1808
16. Address 1248 RALPH AVENUE City BROOKLYN State NY Zip 11236

V. THIRD PARTY AIR MONITOR

17. Name WARREN & PANZER ENGINEERS 18. Contact Person MICHAEL NOLAN
19. Federal Employer ID. # PII 20. Tel. # (212) 922-0077 Fax # (212) 922-0630
21. Address 228 EAST 45TH STREET City NEW YORK State NY Zip 10017
22. Sample Analysis Laboratory _____ 23. NYS DOH ELAP # _____

VI. PROJECT INFORMATION

24. Starting date for this portion of work 07/22/02 Projected completion date 08/22/02

Asbestos work schedule ☒ Monday ☒ Tuesday ☒ Wednesday ☒ Thursday ☒ Friday ☒ Saturday ☒ Sunday


Shift from: 8⁰⁰ ☒ am ☐ pm to 8⁰⁰ ☐ am ☒ pm

If other,
specify _____

Access to inspect the premises must be provided during the work schedule indicated in this item.

25. Total amount of asbestos-containing material to be abated during this work

5090 Square Feet, and/or 0 Linear Feet



NYC DEPT OF ENVIRONMENTAL PROTECTION
ASBESTOS CONTROL PROGRAM
TRU 2

ACP 7
2/2001

Asbestos Inspection Report

Premise No. 102-104 FULTON STREET					Inspection Date: AS NOTED	
Floor FACADE	Zip 10038	Borough 1	Block 78	Lot 21	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name LEGACY FULTON		
Address City 228 East 45 Street New York				Address City 111 GREAT NECK ROAD GREAT NECK		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone NY 11021 (516) 466-4992		
Contact Person ONSITE: MARC KREFT OFFICE: YAIR LIVY				Time of Inspection from: AS NOTED		

MONDAY JULY 22, 2002

8:00AM - 2:00PM SCAFFOLDING (MOVING SWING) SET UP FOR THE FACADE CLEAN-UP OF THE PREMISE. VACUUMING AND WASHING WILL BE DONE TOMORROW.

TUESDAY JULY 23, 2002

8:00AM WORKERS BEGIN VACUUMING OF BULK DEBRIS FROM THE WINDOW LEDGES AND THE FACADE SURFACE.

12:30PM VACUUMING OF BULK MATERIAL HAS BEEN COMPLETED. WORKERS BREAK FOR LUNCH.

1:00PM WASHING OF FACADE (NORTH - FULTON STREET) BEGINS.

5:00PM WASHING OF FACADE HAS BEEN COMPLETED.

5:00PM - 5:20PM I CONDUCT A VISUAL OF THE CLEANED FACADE SURFACES AND OBSERVE NO VISIBLE WTC DEBRIS. AIR SAMPLING FOR THIS PROJECT WAS PERFORMED BY JOHN BOYD OF WARREN & PANZER ENGINEERS. FIVE AIR SAMPLES WERE RUN ON THE SIDEWALK OUTSIDE THE WORK AREA.

5:30PM WORKERS BEGIN DISMANTLING THE PLASTIC DYKE USED TO COLLECT RUN-OFF WATER FROM THE FACADE CLEAN-UP. BAG-OUT ACTIVITIES BEGIN.

6:00PM BAG-OUT ACTIVITIES ARE COMPLETED. WORKERS LEAVE THE JOBSITE. THE CLEAN UP FOR THIS PREMISE IS NOW COMPLETED.

230 East 45th Street
New York, NY 10017
(212) 922-0077
Fax (212) 922-9630

T020724G

WARREN & PANZER ENGINEERS, P.C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE 1 OF 1

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate ^{+/a} RECEIVED

CLIENT: NYC DEP

PROJECT: 104 Fulton

LOCATION: FULFIDE

W&P FILE #: 1074-24-02

LABORATORY: WKP

ANALYSIS METHOD: PCM

circle one

TECHNICIAN:

RAF CONSULTANTS

CONTACT: Mike Nolan

2007 JUL 21 11:52

P.O.

SAMPLE NUMBER	SAMPLE DESCRIPTION/LOCATION	SAMPLE TYPE	PUMP #	FLOWRATE START	STOP	TIME ON	TIME OFF	TOTAL TIME	VOLUME (liters)	CONCENTR. (lb./cc.)
207202 01	Near Train station	3		4	4	0942	1720	450	1800	
207202 02	right side of building	3		4	4	0942	1722	450	1800	
207202 03	Left side of building	3		4	4	0944	1724	480	1800	
207202 04	by east door (left)	3		4	4	0945	1725	450	1800	
207202 05	by east door (right)	3		4	4	0946	1726	450	1800	
207202 06	Field Blank	1		N/A	N/A	0	0	0	0	
207202 07	1	1		N/A	N/A	0	0	0	0	
207202 08	Sealed Blank	1		N/A	N/A	0	0	0	0	

COMMENTS:

SAMPLE BY: John Boyd DATE: 7/23/07
SIGNATURE: John Boyd
RELEASED BY: John Boyd DATE: 7/23/07
SIGNATURE: John Boyd
RECEIVED BY: B. OREN KAM DATE: 7/24/07
SIGNATURE: David

SAMPLE TYPE CODES			
1 - Blank	5 - Final Clearance (inside)		
2 - Pre-Abatement	6 - Final Clearance (outside)		
3 - During Abatement	7 - Personal		
4 - During Glove Bag Removal	8 - Background		

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

ANALYSIS REPORT

ASBESTOS IN AIR

Transmission Electron Microscopy

CLIENT: WARREN & PANZER
PROJECT: 104 Fulton - Fuaade

Lab ID#	Client Sample ID#	Sample Location	Volume (liters)	Grid Openings (microns)	Filter Area (mm ²)	Analytical Sensitivity (sfm/cc air)	Adhesion Type(s)	Asbestos Structures (microns)	Detected	Structure Density (structures/cm ²)	Structure Density (structures/cm ²)	Structure Density (structures/cm ²)
								0.5-5.0	>5.0	Total		Total
70207246-01	VB 97262		1800	5	385	0.0043	ND	0	0	0	<20.00	<0.0043
T -02	-02											
T -03	-03											
T -04	-04											
T -05	-05											
T -06												
T -07												
T -08												
T -09												
T -10												

Date Received: 7/24/02
Date Analyzed: 7/25/02
Date of Report: 7/25/02

Area Analyzed: 0.250 0 mm²
Grid Opening Area: 0.007377 mm² - 0.0 (0.0)
Date Collected: 7/23/02

Analyst: David Chen

Lab Director: George Kouvaras

Analysis performed according to NIOSH Method (EPA 40 CFR Part 163 - Appendix A). Samples will be stored for thirty (30) days and then returned to the client upon request.

NIOSH ELAP# 11223

NIST-NVLAB # 602047

ADHA #: 800789

IESI NY CORPORATION

110 5th Street • Brooklyn, NY 11215

Phone: 718-522-2263 • Fax: 718-522-2697

MANIFEST

11777

DATE 8/13/02

GENERATOR	1. Job Site Address 102-104 Fulton Street Brooklyn, N.Y. New York		Owner Dept Of Enviro Protection	Wait and Load Time In _____ Time Out _____
	2. Consignor Address Benjamin Kurzban & Son 1248 Ralph Avenue Brooklyn, NY 11236		Drop Date	
	3. Waste disposal site (WDS) name, mailing address and physical site location IESI Pa Blue Ridge Landfill Corporation P.O. Box 398 Scotland, Pa. 17254		WDS phone number Permit # 100934	
	4. Name and address responsible agency (Local, District or EPA Office where notification was sent) US EPA 290 Broadway, New York 10007			
TRANSPORTER	5. Description of materials (RQ) WASTE ASBESTOS 9, NA2212, III	6. VEH. LIC. # 29696 PA TYPE CLOSED SIZE 40 YD	7. TOTAL QUANTITY 2 CUBIC YARDS	
	8. Generator Certification Box # 4024	Trc 11479		
	9. CONTRACTOR CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international government regulations.			
WASTE SITE	Printed/Typed Name _____ Title _____ Signature _____		Date (M/D/Y) XXXXX NJ-462	
	10. Transporter #1 (Acknowledgement of receipt of materials) IESI NY CORPORATION • 110 5th Street, Brooklyn, NY 11215		DEC Permit No. JA-462	
	Printed/Typed Name Philip Crima Title DRIVER Signature [Signature]		Date (M/D/Y) NJ-462	
	11. Transporter #2 (Acknowledgement of receipt of materials)		DEC PERMIT #	
Printed/Typed Name Jessie Title DEI Signature [Signature]		Date (M/D/Y) 8/15/02		
12. Discrepancy indication space				
13. Waste disposal site owner or operator: Certification of receipt of asbestos materials covered by this manifest except as noted in item #12				
Printed/Typed Name Katrina K. Kirk Title Gatekeeper Signature KKK		Date (M/D/Y) 8/16/02		

WHITE:LANDFILL • GREEN:IESI • PINK:GENERATOR • YELLOW:CONTRACTOR • GOLD:JOB SITE