

IESI NY CORPORATION

110 5th Street • Brooklyn, NY 11215
Phone: 718-522-2263 • Fax: 718-522-2697

MANIFEST

11777

DATE 8/13/02

G E N E R A T O R	1. Job Site Address 100-104 Fulton Street Brooklyn, N.Y. New York		Owner Dept Of Enviro Protection	Wait and Load Time In _____ Time Out _____	
	2. Contractor Name and address Benjamin Kurzban & Son 1248 Ralph Avenue Brooklyn, NY 11236		Drop Date		
	3. Waste disposal site (WDS) name, mailing address and physical site location IESI Pa Blue Ridge Landfill Corporation P.O. Box 300 Scotland, Pa. 17254		WDS phone number Permit # 100934		
	4. Name and address responsible agency (Local, District or EPA Office where notification was sent) US EPA 290 Broadway, New York 10007				
T R A N S P O R T E R	5. Description of materials (RQ) WASTE ASBESTOS 9, NA2212, III		6. VEH. LIC. # 29696 MA	7. TOTAL QUANTITY	
			TYPE CLOSED	BAGS	
			SIZE 40 YD CR	2 CUBIC YARDS	
	8. Generator Certification		Box # 4024	T/C 11479	
W A S T E S I T E	9. CONTRACTOR CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked and labeled, and are in all respects in proper condition for transport by highway according to applicable international government regulations.				
	Printed/Typed Name _____		Title _____	Signature _____	Date (M/D/Y) XXXXXX NJ-462
	10. Transporter #1 (Acknowledgement of receipt of materials) IESI NY CORPORATION • 110 5th Street, Brooklyn, NY 11215			DEC Permit No. JA-462	
	Printed/Typed Name Philip C. Maria		Title DRIVER	Signature [Signature]	Date (M/D/Y) NJ-462
	11. Transporter #2 (Acknowledgement of receipt of materials)			DEC PERMIT #	
	Printed/Typed Name JESUS		Title DR	Signature [Signature]	Date (M/D/Y) 8/15/02
12. Discrepancy indication space					
13. Waste disposal site owner or operator: Certification of receipt of asbestos materials covered by this manifest except as noted in item #12					
Printed/Typed Name Katrina K. Kirk		Title Gatekeeper	Signature KKK	Date (M/D/Y) 8/16/02	

WHITE:LANDFILL • GREEN:IESI • PINK:GENERATOR • YELLOW:CONTRACTOR • GOLD:JOB SITE

Asbestos Inspection Report

Premise No. 102-104 FULTON STREET					Inspection Date: AS NOTED	
Floor FACADE	Zip 10038	Borough 1	Block 78	Lot 21	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name LEGACY FULTON		
Address City 228 East 45 Street New York				Address City 111 GREAT NECK ROAD GREAT NECK		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone NY 11021 (516) 466-4992		
Contact Person ONSITE: MARC KREFT OFFICE: YAIR LIVY				Time of Inspection from: AS NOTED		

MONDAY JULY 22, 2002

8:00AM - 2:00PM SCAFFOLDING (MOVING SWING) SET UP FOR THE FACADE CLEAN-UP OF THE PREMISE. VACUUMING AND WASHING WILL BE DONE TOMORROW.

TUESDAY JULY 23, 2002

8:00AM WORKERS BEGIN VACUUMING OF BULK DEBRIS FROM THE WINDOW LEDGES AND THE FACADE SURFACE.

12:30PM VACUUMING OF BULK MATERIAL HAS BEEN COMPLETED. WORKERS BREAK FOR LUNCH.

1:00PM WASHING OF FACADE (NORTH - FULTON STREET) BEGINS.

5:00PM WASHING OF FACADE HAS BEEN COMPLETED.

5:00PM - 5:20PM I CONDUCT A VISUAL OF THE CLEANED FACADE SURFACES AND OBSERVE NO VISIBLE WTC DEBRIS. AIR SAMPLING FOR THIS PROJECT WAS PERFORMED BY JOHN BOYD OF WARREN & PANZER ENGINEERS. FIVE AIR SAMPLES WERE RUN ON THE SIDEWALK OUTSIDE THE WORK AREA.

5:30PM WORKERS BEGIN DISMANTLING THE PLASTIC DYKE USED TO COLLECT RUN-OFF WATER FROM THE FACADE CLEAN-UP. BAG-OUT ACTIVITIES BEGIN.

6:00PM BAG-OUT ACTIVITIES ARE COMPLETED. WORKERS LEAVE THE JOBSITE. THE CLEAN UP FOR THIS PREMISE IS NOW COMPLETED.

Asbestos Inspection Report

Premise No. 102-104 FULTON STREET					Inspection Date: AS NOTED	
Floor FACADE	Zip 10038	Borough 1	Block 78	Lot 21	Squad # N/A	Badge # A020
Inspector Dennis Antzoulatos		Building Type COMMERCIAL		Basis of Inspection WTC Survey		Photos Taken ☒ Yes ☐ No
Contractor's Name Benjamin Kurzban & Son Control				Sample Number N/A		
Address City 1248 Ralph Avenue, Brooklyn				Sample Number N/A		
State Zip Phone NY 11236 (718)531-2900				Sample Number N/A		
Laboratory Name Warren & Panzer Engineers Inc.				Owner's Name LEGACY FULTON		
Address City 228 East 45 Street New York				Address City 111 GREAT NECK ROAD GREAT NECK		
State Zip Phone NY 10017 (212) 922-0077				State Zip Phone NY 11021 (516) 466-4992		
Contact Person ONSITE: MARC KREFT OFFICE: YAIR LIVY				Time of Inspection from: AS NOTED		
<u>MONDAY JULY 22, 2002</u> 8:00AM - 2:00PM SCAFFOLDING (MOVING SWING) SET UP FOR THE FACADE CLEAN-UP OF THE PREMISE. VACUUMING AND WASHING WILL BE DONE TOMORROW.						
<u>TUESDAY JULY 23, 2002</u> 8:00AM WORKERS BEGIN VACUUMING OF BULK DEBRIS FROM THE WINDOW LEDGES AND THE FACADE SURFACE. 12:30PM VACUUMING OF BULK MATERIAL HAS BEEN COMPLETED. WORKERS BREAK FOR LUNCH. 1:00PM WASHING OF FACADE (NORTH - FULTON STREET) BEGINS. 5:00PM WASHING OF FACADE HAS BEEN COMPLETED. 5:00PM - 5:20PM I CONDUCT A VISUAL OF THE CLEANED FACADE SURFACES AND OBSERVE NO VISIBLE WTC DEBRIS. AIR SAMPLING FOR THIS PROJECT WAS PERFORMED BY JOHN BOYD OF WARREN & PANZER ENGINEERS. FIVE AIR SAMPLES WERE RUN ON THE SIDEWALK OUTSIDE THE WORK AREA. 5:30PM WORKERS BEGIN DISMANTLING THE PLASTIC DYKE USED TO COLLECT RUN-OFF WATER FROM THE FACADE CLEAN-UP. BAG-OUT ACTIVITIES BEGIN. 6:00PM BAG-OUT ACTIVITIES ARE COMPLETED. WORKERS LEAVE THE JOBSITE. THE CLEAN UP FOR THIS PREMISE IS NOW COMPLETED.						