

**228 East 45th Street
New York, NY 10017
(212) 922-9077
Fax (212) 922-0630**

WARREN & PANZER ENGINEERS, P. C.
AIR MONITORING LOG SHEET/CHAIN-OF-CUSTODY FORM

PAGE _____ OF _____

500 

Fax (212) 922-0830

24 hr⁺/a 12 hr⁺/a 6 hr⁺/a 3 hr⁺/a Immediate⁺/a

P.O.

CLIENT: NYC DEP

W&P FILE #: 1079, 01, 02

CONTACT: Michael Nolan

PROJECT: ROOF & FACADES

ANALYTICAL METHOD: GRAVIMETRIC

ANALYSIS METHOD: PCM TEM

LOCATION: 111 Fulton St., NY, NY

circle one	AHERA	EPA LEVEL II
7400		

TECHNICIAN: MARIA SEGALINE

[illegible]

COMMENTS:

SAMPLE BY: Maria SEGALINE DATE: 7-25-02

SIGNATURE: M. J. Regalino

RELEASED BY: MARIA SCALONE DATE: 7-25-01

SIGNATURE: Mavis Regalino

RECEIVED BY: *[Signature]* DATE: 7-28-12

SIGNATURE: *M. W. [Signature]*

SAMPLE TYPE CODES	
1 - Blank	5 - Final Clearance (inside)
2 - Pre-Abatement	6 - Final Clearance (outside)
3 - During Abatement	7 - Personal
4 - During Glove Bag Removal	8 - Background

SEE REVERSE SIDE FOR ANALYSIS INFORMATION

TESTWELL LABORATORIES, INC.
ENVIRONMENTAL DIVISION

PAGE 1 OF 1

DATE: 7/30/02

ASBESTOS LABORATORY

TEM AIR SUMMARY SHEET

CLIENT: Warren & PanzerPROJECT: NYC Dep/ Roof & FacadesMETHOD: AHERA

CLIENT NUMBER	LAB # 01 TEM -	VOLUME COLLECTED (L)	GRID OPENINGS ANALYZED	GRID AREA ANALYZED (mm ²)	COUNTABLE ASBESTOS STRUCTURES PER SAMPLE	CONCENTRATION (Structures/mm ²)	CONCENTRATION (Structures/cc)
001	5221	1800.0	4	0.048	0	< 20.66	< 0.004
002	5222	1800.0	4	0.048	0	< 20.66	< 0.004
003	5223	1800.0	4	0.048	0	< 20.66	< 0.004
004	5224	1800.0	4	0.048	0	< 20.66	< 0.004
005	5225	1800.0	4	0.048	0	< 20.66	< 0.004

	Structures/mm ²	Structures/cc
TOTAL AVERAGE CONCENTRATIONS	< 20.66	< 0.004

NOTE: When no asbestos structures are counted, the Analytical Sensitivity Detection Limit is reported.

COMMENTS: _____

ANALYST'S SIGNATURE: 