

WTC Visual Survey Form

Premise Address: 111 FULTON STREET		
Block:	Residential ☐ Commercial ☒	Name of Building:
Lot:	Mix Use ☐ Other ☐	
# of Stories:	AKA's: 151 WILLIAM STREET AND 60 ANN STREET	
Building Owner/Management: 224 W 30 LLC DBA/		Telephone Number: (212) 924-9690
Name: 151 WILLIAM OPERATING LLC		FAX: () EXT 207
Address: 111 FULTON ST NY NY		
On Site Contact: BLDG ENGINEER @ SITE: DENNIS		
Name: SUSAN DONOHUE (OFFICE @ 156 WILLIAM ST)		Telephone Number: (212) 924-9690 EXT 207
Building Owner Management Activities		
Interior Survey Performed ☐ Yes ☐ No		
Exterior Survey Performed ☐ Yes ☐ No		
General Clean Up ☐ Yes ☐ No Locations: _____		
ACM Clean Up ☐ Yes ☐ No Locations: _____		
Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
		Inspected	Debris		
North	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☒ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Facade Description: FINE LAYER ON WINDOWS (LOWER FLOORS)					
Roof					
Debris: ☐ No Visible /Fine Layer ☒ ½ to 1" ☐ > 1"					
Description: MATERIAL IS LOCATED BENEATH THE STONES					
Setbacks N/A ☒					
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Floor: _____	Debris:	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"	
Comments					

Date: 07 / 12 /2002

Inspection Team: Name: DA /A020
Name: _____Agency: NYC DEP
Agency: _____