

WTC Visual Survey Form

1001206

Premise Address: 122 Fulton Street		
Block: 78 Lot: 44	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐	Name of Building:
# of Stories:	AKA's:	
Building Owner/Management: Name:		Telephone Number: () FAX: ()
Address:		
On Site Contact: Name:		Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____		
Copies of All Reports and Data Requested ☐ Yes		

Visual Inspection Results:

Facade:					
North	☐ N/A	Inspected	Debris	☒ 1/2 to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"
Facade Description: _____ _____					
Roof					
Debris: ☐ No Visible /Fine Layer		☒ 1/2 to 1" ☐ > 1"			
Description: _____ _____					
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ 1/2 to 1"	☐ > 1"		
Comments _____ _____ _____ _____					

Date: 2/17/2002

Inspection by: Name: AP
Name: _____

Agency: DEP
Agency: _____

February 17, 2002



The City of New York
Department of Environmental Protection

59-17 Junction Boulevard
 Corona, New York
 11368-5107

Joel A. Miele Sr., P.E.
Commissioner

Robert C. Avaltroni
Deputy Commissioner

Bureau of Environmental Compliance
 Tel (718) 595-4418
 Fax (718) 595-4422

Building Owner Name: JAMIAARD Partners

Address:

122 Fulton St
NYC
NYC

Subject: _____

Dear Sir/Madam:

In September 2001, the New York City Department of Environmental Protection (NYCDEP) and the Department of Health (NYCDOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the assessment of building contamination for possible hazardous components, including asbestos.

Today, a visual survey of your building's exterior was conducted as a follow up to DEP's October survey of buildings around the World Trade Center site. At the above-referenced site, visible dust accumulations were observed at:

- ☒ building facade(s)
- ☒ setback(s)
- ☒ roof
- ☐ other, _____

Please be advised building owners are responsible for the cleaning of building exteriors, grounds and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

Please provide information regarding your actions to address the dust accumulations by February 27, 2002. Copies of the environmental hazard assessments including bulk sample results, air monitoring results and/or a summary of clean-up activities at the above-referenced site may be faxed to (718) 595-3744 or sent to the NYCDEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

If you have any questions, you may reach the NYCDEP at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. NYCDEP staff is available to provide guidance and technical assistance.

Sincerely,

R. Radhakrishnan, P.E.
 Director
 Asbestos Control Program





**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**
Bureau of
Environmental Compliance
Tel (718) 595-4418
Fax (718) 595-4422

February 17, 2002

Building Owner Name: _____

Address: _____

122 Fulton St
NYC

Subject: _____

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Due to changing conditions and continued activity at Ground Zero, building owners should periodically assess the condition of building exteriors and air conditioning systems for cleanliness and may have to periodically re-clean areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

[Signature]
**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**



www.nyc.gov/dep

(718) DEP-HELP