

NYC DEP

59-17 Junction Blvd.
Corona, NY 11368
(718)DEP-HELP Fax (718)595-4096

Service Request Dispatch Detail

Report Date 04/17/2002 12:13 PM

Submitted By

Page 1

Service # 435348
Problem B1 ASBESTOS COMPLAINT
Address 150 FRANKLIN ST 1
10013
Cross Streets VARICK ST
HUDSON ST
Compass Direction
Building ID 10021 Block 00189 Lot 0007 CMBD 101
Location
Area District
Sub-Area 101 Parcel
of Calls 1 Duration of Call 00:00 Call Date 04/17/2002 10:03
Taken By 7284 HOLMES, AISHA
Responsibility BHZ BANHAZMAT (AIR, NOISE, HAZ. MAT) Priority
Scheduled Date
Inspector
Due Date
Asset
Avg Insp Duration
Avg Insp Days 0
Avg Insp Hrs 0
Avg Insp Mins 0
Customer Contact Req
Budget #

Problem Comments

Initial Caller

Last Name
First Name, MI
Address

PII

Title MR

City, State/Province, ZIP/PC

Foreign

Day Phone

Reference #

PII

Evening Phone

Call Date 04/17/2002 10:03

Caller Comments

ASBESTOS BEING ILLEGALLY REMOVED IN BLDG. BY CONTRACTORS.//DAYCARE IN BLDG//DUST ANALYZED OVER 1%//PLS. RESPOND ASAP//CONTRACTORS ARE OUT NOW//SPOKE TO LIZ//BUZZ CASTE TOP BUZZER

Inspected				Resolution			
By	Ram	Date	4/17/02	Time	11:30	Code	2
		Date	4/17/02	Time	1:00 pm		

There was no roof removal or illegal removal observed in the building. The only work observed was at the staircase in 7th floor involving sheetrock removal. NO suspect ACM observed in stair case. On the roof EPA inspector collected samples of dust and charcoal debris in a corner. The 7th floor complainant claimed that the debris was observed in July 2001. In the 3rd floor elevator shaft window ~~edge~~ ledges accumulation of old dust observed and the windows were broken. EPA also collected ~~by~~ samples. I collected one sample. ~~SPE~~ ^{EPA} sampler of roof 2 nos: and window ~~edge~~ ledge sample 1st, and a DEP sample from 3rd floor elevator shaft window ledge. EPA samples of TEM analysis by an independent lab came out positive for asbestos. A clean up was advised to the co-op Board and clean-up ~~is~~ in progress as of 4/19/02