

WTC Visual Survey Form

Premise Address: 225/227/229 Front St. 225 Front St. 97/24
1001336-L

Block: 225 Residential ☐ Commercial ☐ Name of Building: 227 Front St 97/25
Lot: 227 Mix Use ☐ Other ☐ 1001337-L

of Stories: 5 AKA's: 229 Front St - 97/26

Building Owner/Management: Telephone Number: () 1079112-L
Name: FAX: ()

Address:

On Site Contact: Vacant Telephone Number: ()

Building Owner Management Activities

Interior Survey Performed ☐ Yes ☐ No

Exterior Survey Performed ☐ Yes ☐ No

General Clean Up ☐ Yes ☐ No Locations: _____

ACM Clean Up ☐ Yes ☐ No Locations: _____

Air Monitoring ☐ Yes ☐ No Locations: _____

Copies of All Reports and Data Requested ☐ Yes

Visual Inspection Results:

Facade:

		Inspected	Debris		
North	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
South	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Facade Description: Buildings enclosed in safety net around scaffold

Roof

Debris: ☐ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"

Description: _____

Setbacks N/A ☐

Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"

Comments

Date: 5/18/2002Inspection Team: Name: CARL

Agency: _____

Name: _____

Agency: _____