

Theodorellys, Penny

From: Lutchmedial, Carlstien
Sent: Friday, June 16, 2006 4:15 PM
To: Radhakrishnan, Krish; Theodorellys, Penny
Subject: WTC Inspections

Today, I inspected the following buildings:

1. 214 -220 Front Street - vacant, a buildings department permit is posted at the store entrance. At the entrance to the tenants spaces, pressing the buzzers produced no response. These are private apartments with no superintendent or management office.. The facade of the building looked very clean with no visible debris.
2. 227 Front Street - At the entrance to the tenants spaces, pressing the buzzers produced no response. These are private apartments with no superintendent or management office.. The facade of the building looked very clean with no visible debris. A sign on the door stated that the store is for rent "Call DF Realty - 212-216-9777."
3. 229 - 231 Front Street - Unable to gain access. At the entrance to the tenants spaces, pressing the buzzers produced no response. These are private apartments with no superintendent or management office.. The facade of the building looked very clean with no visible debris.

Premises Address: 225/227/229 Front St. 225 Front St. 97/24 1001336-L	
Block: Lot:	Residential ☐ Commercial ☐ Mix Use ☐ Other ☐
Name of Building: 227 Front St 97/25 1001337-L	
# of Stories: 5	AKA's: 229 Front St - 97/26
Building Owner/Management Name:	Telephone Number: () 1079112-L FAX: ()
Address:	
On Site Contact: Name: Vacant Telephone Number: ()	
Building Owner Management Activities	
Interior Survey Performed ☐ Yes ☐ No	
Exterior Survey Performed ☐ Yes ☐ No	
General Clean Up ☐ Yes ☐ No	Locations: _____
ACM Clean Up ☐ Yes ☐ No	Locations: _____
Air Monitoring ☐ Yes ☐ No	Locations: _____
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:					
North ☐ N/A South ☐ N/A East ☐ N/A West ☐ N/A	Inspected ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No		Debris ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1" ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"		
	Facade Description: Buildings enclosed in safety net around scaffold				
	Roof				
	Debris: ☐ No Visible /Fine Layer ☐ 1/2 to 1" ☐ > 1" Description: _____				
Setbacks N/A ☐					
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"				
Floor: _____	Debris: ☐ No Visible/Fine Layer ☐ 1/2 to 1" ☐ > 1"				
Comments					

Date: 5/18/2002 **Inspection Team Name:** CARE **Agency:** _____
Name: _____ **Agency:** _____