

NYC Visual Survey Form

Premise Address: <u>244 FRONT Street</u>	
Block:	Residential ☐ Commercial ☒ Name of Building:
Lot:	Mix Use ☐ Other ☐
# of Stories:	AKA's:
Building Owner/Management:	Telephone Number: ()
Name:	FAX: ()
Address:	
On Site Contact:	Telephone Number: ()
Building Owner Management Activities Interior Survey Performed ☐ Yes ☐ No Exterior Survey Performed ☐ Yes ☐ No General Clean Up ☐ Yes ☐ No Locations: _____ ACM Clean Up ☐ Yes ☐ No Locations: _____ Air Monitoring ☐ Yes ☐ No Locations: _____	
Copies of All Reports and Data Requested ☐ Yes	

Visual Inspection Results:

Facade:					
North	☒ N/A	Inspected	Debris	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"
South	☒ N/A	☒ Yes ☐ No	☒ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
East	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
West	☐ N/A	☐ Yes ☐ No	☐ No Visible/Fine Layer	☐ ½ to 1" ☐ > 1"	
Facade Description:					
Roof					
Debris: ☒ No Visible /Fine Layer ☐ ½ to 1" ☐ > 1"					
Description: _____					
Setbacks ☒ N/A					
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Floor: _____	Debris: ☐ No Visible/Fine Layer	☐ ½ to 1"	☐ > 1"		
Comments					

Date: 4 / 20 / 2002

Inspection Team: Name: Sam Nebedum Agency: _____
 Name: Robin exello Agency: _____

ENTERED



**Department of
Environmental
Protection**

59-17 Junction Boulevard
Corona, New York
11368-5107

**Joel A. Miele Sr., P.E.
Commissioner**

**Robert C. Avaltroni
Deputy Commissioner**

**Bureau of
Environmental Compliance**
Tel (718) 595-4418
Fax (718) 595-4422

April ____, 2002

20

Building Owner Name: _____

Address: 244 Front St

Subject: 244 Front St

Dear Sir/ Madam:

In September 2001, the New York City Department and Environmental Protection (NYC DEP) and the Department of Health (NYC DOH) advised building owners regarding building maintenance and re-occupancy issues following the collapse of the World Trade Center. The steps included the professional assessment of building contamination for possible hazardous components, including asbestos, and a retrospective filing, as required, if applicable.

The NYC DEP is hereby requesting copies of the environmental hazard assessments including bulk sample results and air monitoring results and a summary of clean-up activities at the above referenced site. Please forward the requested documents to our offices within FIVE BUSINESS DAYS. They may be faxed to (718) 595-3744 or sent to the NYC DEP Asbestos Control Program at 59-17 Junction Boulevard, 8th floor, Corona, New York 11373-5108.

Please be advised building owners are responsible for the cleaning of building exteriors, grounds, and common areas. Adherence to proper cleaning methods is important for the protection of public health and the environment. DEP inspectors will be following up on this matter.

If you have any questions, you may reach the Department at (718) 595-3682 during office hours or the 24-hour Help Center at (718) DEP-HELP. DEP staff is available to provide guidance and technical assistance.

Sincerely,

R.
**R. Radhakrishnan, P.E.
Director
Asbestos Control Program**

FW



www.nyc.gov/dep

(718) DEP-HELP

Page: 1 Document Name: Extra

```

04/24/02          N.Y.C. DEPARTMENT OF BUILDINGS          BISPIQ31
          MULTI-AGENCY COMPOSITE PROPERTY & OWNER INFORMATION QUERY
244..... FRONT STREET..... 1 MANHATTAN          10038 BIN# 1001380
DCP GEOGRAPHICAL INFORMATION:
FRONT STREET          244 - 244          HEALTH AREA : 77          TAX BLK: 107..
          CENSUS TRACT: 11001          TAX LOT: 35...
          COMMUNITY BD: 101          CONDO :
          MULTI STRUCT: 1          CUI NO :
DOF OWNER NAME & ADDRESS FROM BILLING FILE: DOF OWNER NAME FROM PROPERTY FILE
OWNER NAME : 144 FRANT ST ASSOCIATES          144 FRANT ST ASSOCIAT
CORP. NAME :          LPC LANDMARK STATUS: LANDMARK
ADDRESS : 244          W 99TH ST          DOB LOCAL LAW STATUS: NO
          NEW YORK NY 10025-5433
DOF BUILDING INFORMATION:          TRANS LAND VALUE: 804.000
BLDG SIZE: 0027.00 X 0082.00          TAX EXEMPT FLAG : NO
LOT SIZE: 0027.33 X 0085.17          TAX EXEMPT CLASS:
BLDG CLASS : D0 ELEVATOR APT          CITY OWNERSHIP : NO
STORIES : 6          UPDATE DATE : 03/25/02
FOR CITY } MGMT TYPE:          MGMT CODE:          MGMT CODE NAME:
OWNERSHIP }          MGMT HOLDER CODE:          MGMT HOLDER CODE NAME:
-----
PF1 =PREV  PF2 =MAIN  PF7 = NEW ADDRESS  PF8 = NEW BLK/LOT  PF9 = NEW BIN

```

Date: 4/24/ 2 Time: 02:21:16 PM